


16. porch details: checked posts (CP1) turned posts (CP2) supports on pedestals (CP3) columns (CL1) posts (CP4) piers (P1) pillars (PL) freestanding posts (CP5) balustrade (BA) heavy work wall (HW1) turned balustrade (TB) cast balustrade (CB) cast balustrade (CL) other cast/turned work (CT) enclosed and bay (EB1) insect screening (IS) other (O)
17. window: single (S1) double (S2) paired (P1) tripartite (TP1) grouped (GP) decorative (DC) slatex (SL) other (O)
18. pane configuration:  tripartite (T1) clear area (CA) black glass (BB) tungsten/bronze/glass (TB) other (O)
19. doors: single (S1) double (S2) transoms (TR) fanlight (FL) sidelights (SL) other (O)
20. decorative element material: cast iron (CI) cast stone (CS) terra cotta (TC) granite (GR) wood (WO) pressed metal (PM) marble (MR) other (O)
21. interior features: _____

22. HISTORIC: none (N) none visible (NV) garage (GR) garage w/living area (GLA) shed (SH) kitchen (KT)
23. USE/USE/FORM: farm house (FH) other house (OH) office (OF) barn (BR) tobacco barn (TBR) dairy (DA) crib (CR) warehouse (WH) view house (VH) privy (PV) well (WL) springhouse (SP) store (ST) other (O)
24. SURROUNDING: residential (R) residential/commercial (RC) commercial (C) rural (RU) rural community (RCU) industrial (IN) other (O)

25. ADDITIONAL DESCRIPTIVE COMMENTS: Cross gable roof with rear gable extension. Front projecting gable bay has boxed cornice with return, supported by brackets with pendants, decorative wood above 1/1 window in gable end. Two entry doors with entablature surrounds. Porch with wood deck has paired pillars on brick pedestals; concrete deck extends to right elevation, with brick pedestals. Side gable projection similar to front. Right elevation has single and double 5/6 windows.

26. ALTERNATE: Asbestos shingle siding

GENERAL INFORMATION

27. SUBJECT: _____
28. SUBJECT: _____
29. SUBJECT: _____
30. ARCHITECT: _____ SOURCE: _____
31. BUILDER: _____ SOURCE: _____
32. HISTORICAL DATA: Appears on 1910 and 1916 Sanborn maps. 1914 Rates Book lists Mrs. M. E. Husey as OWNER. 1936 City Directory lists Mrs. Edna Caution, supervisor with WPA Sewing Room, and J. Benjamin Stewart, teacher at Rock Hill High School, as occupants.

33. INFORMATION SOURCE

34. PROJECT NUMBER
35. SURVEYOR NAME: Rock Hill 36. PHOTOGRAPHIC: prints Y slides _____ negatives Y
37. OTHER DOCUMENTATION: survey field notes (SF) national register files (NF) tax art files (TA) grants files (GF) state historical marker files (SM) environmental review files (ER) other (O) _____
38. RECORD MAINTENANCE: ORC, Preservation Consultants, Inc.
39. DATE RECORDED: 8/11/10
40. COMMENTS: _____



DESCRIPTION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
Survey Field Formplate Entry Form
2025 Historic Preservation Office
PO Box 11,609 Columbia, SC 29211
(803)796-8377

CONTROL NUMBER: 18791 11987429 563
county census dist. or site number
 rated place

CONTINUATION:



EXPOSURE

1

VIEW OF

FRONT (S.W. CORNER)

DATE TAKEN: 5/11/68
PREPARED BY: DR. P. W. B. SCHLESINGER

