



- 3) porch details: overhead posts (OP) turned posts (TP) supports on pedestals (SP) columns (CP) posts (PP) piers (PI) pillars (PL) freestanding posts (FP) balustrade (BA) screen upon wall (SW) turned balustrade (TB) cast balustrade (CB) cast balustrade (CB) other (OT) cast balustrade (CB) cast balustrade (CB) other (OT)
- 4) window: single (S) double (D) paired (PD) tripartite (TR) grouped (GR) decorative (OR) display (DR) other (O)
- 5) pane configuration: 6/1 1/1 tripartite (TR) custom frame block glass (CB) burglar/fire/blast resistant (BR) other (O)
- 6) door: single (S) double (D) transoms (TR) fanlight (FL) sidelights (SL) other (O)
- 7) decorative element: cast iron (CI) cast stone (CS) terra cotta (TC) granite (GR) wood (WO) pressed metal (PM) material: marble (MR) other (O)

c) interior features:

- 8) kitchen: none (N) none visible (NV) garage (GA) garage wiring area (GWA) shed (SD) window (WT)
- OUTBUILDINGS: barn house (BH) other house (OH) office (OF) barn (BN) tobacco barn (TB) dairy (DA) crib (CR) washhouse (WH) slave house (SH) privy (PR) well (WL) carriagehouse (CH) store (ST) other (O)
- 9) surroundings: residential (R) residential/commercial (RC) commercial (C) rural (RU) rural community (RC) industrial (IN) other (O)

20. ADDITIONAL DESCRIPTIVE COMMENTS: Small multi-light window in porch gable end; lowered attic vent in front gable end. Right elevation has single and paired windows; left elevation has single and double windows; oversized 6/1 window within porch; wood posts on pedestals. Exposed rafter ends, triangular knee braces at eaves. Beloit pier foundation with brick fill.

21. ALTERNATES: Asbestos shingle siding, awning at porch and facade window, insect screening.

HISTORICAL INFORMATION

22. DEDUCTIONS: \_\_\_\_\_
23. REFERENCES: \_\_\_\_\_
24. IMPORTANT PERSONS: \_\_\_\_\_
25. ACQUISITION: \_\_\_\_\_ SOURCE: \_\_\_\_\_
26. INTERESTS: \_\_\_\_\_ SOURCE: \_\_\_\_\_
27. HISTORICAL DATA: Not shown on 1928 Barbours map, house appears on 1928 map. City Directory for 1929 shows it occupied by Gus E. Baker, a machinist, and in 1936 by Roy S. Baker, proprietor of Baker's Shoe Repair.

28. DISPOSITION/USE CHANGE: \_\_\_\_\_

PROGRAM MANAGEMENT

29. GUARANTEE NAME: Rock Hill 30. PHOTOGRAPHY: (P) prints Y slides \_\_\_\_\_ negatives Y
31. OTHER INFORMATION: survey book-up files (SF) national register files (NF) tax map files (TF) \_\_\_\_\_
- state historical marker files (SM) environmental review files (EM) other (O) \_\_\_\_\_
32. RECORDS MAINTENANCE: DES, Preservation Consultants, Inc.
33. DATE RECORDED: 5/14/03
34. COMMENTS: year work stop



DESCRIPTION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places  
 Historic Field Inventory Entry Form  
 State Historic Preservation Office  
 80 Box 71,000, Columbia, SC 29271  
 (803)76-5117

CONTROL NUMBER: 1101 / 1105 / 424 - 103  
county census design site number  
state design

CONTINUATION:

---

---

---

---

---

---

---

---

---

---



Roll # 1 Sheet 1  
1 of 1 sheets  
 PHOTO (K&A-1100)

Date taken: 8/16/69  
 Recorded by: DEE, Preservation  , Inc.