

10. porch details: clustered posts (20P) tapered posts (20T) supports on pedestals (20P) columns (20C) posts (20I) piers (20) pillars (20) freestanding posts (20F) balustrade (20A) masonry apron wall (20M) turned balustrade (20) cast balustrade (20) cast balustrade (20) other cast/turned work (20T) enclosed and bay (20E) closed screening (20) other (2)

11. windows: single (20A) double (20B) paired (20C) tripartite (20T) grouped (20G) decorative (20D) display (20E) other (20F)

12. pane configuration: double - single - triangular (20) fused glass block glass (20B) integral/overlapped panes (20) other (2)

13. glazing: single (20A) double (20B) tripartite (20T) multiple (20) slat/light (20D) other (2)

14. decorative element: cast iron (20) cast stone (20) terra cotta (20) granite (20) wood (20) pressed metal (20) material: marble (20) other (2)

15. interior features:

16. bathroom: none (20) none suitable (20) garage (20A) garage w/ living area (20B) shed (20C) kitchen (20T)

17. bathroom(s): tenant house (20) other house (20) office (20F) bath (20B) tobacco bath (20C) entry (20E) other (20G)

18. bathroom(s): residential (20) residential/commercial (20) commercial (20) rural (20) rural community (20) industrial (20) other (2)

19. additional descriptive comments: Two other comment windows at first level and at corner bay of continuous shed dormer; outer bays of dormer have double and triple 6/6 windows. Roof has near lateral gable section with shed connection. One-story shed projection at left elevation.

20. alterations:

HISTORICAL INFORMATION

21. THRESHOLD:

22. PREVIOUS:

23. IMPROVED PROPOSED:

24. ARCHITECTURE: SHED

25. MATERIALS: SHED

26. HISTORICAL DATA: Not shown on 1936 Sanborn map, house appears on 1926 map. 1925 City Directory lists this as home of York Wilson, president of William and York Wilson, spot cotton brokers; 1936 Directory lists Archie O. Joslin, manager of Rock Hill Printing and Finishing Company (The Bleachers.)

27. REPORT FILE NUMBER:

PROGRAM ELEMENT

28. LOCATION: Rock Hill 29. PHOTOGRAPHY: prints Y slides negative Y

30. OTHER INFORMATION: curved bedrock files (20) archival register files (20F) tax act files (20G) grants files (20H) archaeological worker files (20I) environmental review files (20J) other (2)

31. DESIGN CONSULTANT: DBS, Preservation Consultants, Inc.

32. DATE REPORTED: SP 01/11

33. COMMENTS:



CONTINUATION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
 Survey Field Form/Data Entry Form
 State Historic Preservation Office
 PO Box 17,669, Columbia, SC 29217
 (803)735-8077

CONTIN. NUMBER: 11 / 51 / 11185 / 474 / 742
COUNTY FEDERAL ID # STATE ID # SITE NUMBER
 16800 (PICK)

CONTINUATION:



Cont.#

1

View#

Facade (East Elevation)

Date taken 09/09/13

Recorded by: DEB. Pomeroy



Inc.