

Dorchester County
Archives and History Center

K) CONSTRUCTION METHOD

- masonry (1)
- frame (2)
- log (5)
- steel (4)
- other (0)

L) EXTERIOR WALLS

- weatherboard (1)
- beaded weatherboard (2)
- shiplap (3)
- flushboard (4)
- wood shingle (5)
- stucco (6)
- tabby (7)
- brick (8)
- brick veneer (9)
- stone veneer (10)
- cast-stone (11)
- marble (12)
- asphalt roll (13)
- synthetic siding (14)
- asbestos shingle (15)
- pigmented structural glass (16)
- other (0)

M) PORCH DETAILS

- chamfered posts (1)
- turned posts (2)
- supports on pedestals (3)
- columns (4)
- posts (5)
- piers (6)
- pillars (7)
- freestanding posts (8)
- balustrade (9)
- apron wall (10)
- turned balusters (11)
- decorative sawn balusters (12)
- slat balusters (13)
- other sawn/turned work (14)
- insect screening (15)
- porte cochere (16)
- other (0)

N) CHIMNEY MATERIAL

- brick (1)
- stuccoed brick (2)
- stone (3)
- brick & stone (4)
- other (0)

O) ROOF MATERIAL

- composition shingle (1)
- pressed metal shingle (2)
- wood shingle (3)
- slate (4)
- raised seam metal (5)
- other metal (6)
- rolled roofing (7)
- not visible (8)
- tile (9)
- other (0)

P) FOUNDATION

- not visible (1)
- brick pier (2)
- brick pier with fill (3)
- brick (4)
- stuccoed masonry (5)
- stone pier (6)
- stone (7)
- concrete block (8)
- slab construction (9)
- basement (10)
- raised basement (11)
- other (0)

Q) DECORATIVE ELEMENT MATERIAL

- cast iron (1)
- pressed metal (2)
- terra cotta (3)
- granite (4)
- marble (5)
- cast stone (6)
- brick (7)
- wood (8)
- pigmented glass (9)
- stone (10)
- stucco (11)
- other (0)

R) INTERIOR FEATURES (list)

18. HISTORIC OUTBUILDINGS AND STRUCTURES:

- | | | | |
|--------------------------|-------------------|------------------|-------------------|
| none (1) | tenant house (7) | crib (13) | store (19) |
| none visible (2) | other house (8) | smokehouse (14) | windmill (20) |
| garage (3) | office (9) | slave house (15) | chicken coop (21) |
| garage w/living area (4) | barn (10) | privy (16) | silos (22) |
| shed (5) | tobacco barn (11) | well (17) | washhouse (23) |
| kitchen (6) | dairy (12) | springhouse (18) | root cellar (24) |
| | | | other (0) |

19. SURROUNDINGS: residential (1) residential/commercial (2) commercial (3) rural (4) rural community (5) industrial (6) other (0)

20. ADDITIONAL DESCRIPTIVE COMMENTS: I: Display windows are fixed with three panes. Brick corbeling at cornice. Left bay of facade is false facade with single door entry into alley adjacent to building.

21. ALTERATIONS

HISTORICAL INFORMATION

22. Theme(s): _____ **23. Period(s):** _____ **24. Important persons:** _____

25. Architect(s): _____ **Source:** _____

26. Builder(s): _____ **Source:** _____

27. Historical data _____

28. Informant/Bibliography Foster, Beth's Pineland Village, 156-157.

PROGRAM MANAGEMENT

29. Quadrangle name: Summerville **30. Photographs:** prints (1) slides (2) negatives (3)

31. Other documentation: survey back-up files (1) National Register files (2) tax act files (3) grant files (4) state historical marker files (5) environmental review files (6) HABS/HAER (7) SCIAA (8) other (0) # _____

32. Recorder name/firm Preservation Consultants: SD **33. Date recorded** 3 / 13 / 1996

