

South Carolina Statewide Survey Site Form
 State Historic Preservation Office
 P.O. Box 11669 • Columbia • SC • 29211 • (803) 734-8609



IDENTIFICATION

1. Control Number U / 35 / 1390 / 496 0306 2. NR Microfiche index # _____
 county census designated place site #

3. Historic name(s): _____

4. Common name: _____

5. Address/location: 201 Central Ave.

City: Summerville Vicinity of: _____ County: Dorchester TMS: 137-07-09-01

6. Ownership: private (1) 2 county (3) state (4) federal (5)
 7. Category: building (1) 2 site (3) structure (3) object (4)
 8. Historic use(s): single dwelling (1) 2 multi dwelling (2) commercial (3) 10. Potential: NR(1) NR historic district (2) archaeological (3)
 other (0)

11. Status/date: listed individually in National Register / / name _____

listed as part of NR historic district 5 / 1976 Name of district Summerville Historic District (#496-008)
 contributing non-contributing _____
 listed individually National Historic Landmark / /
 determined eligible—owner objection / / _____
 determined NOT eligible / / _____
 deferred by review board / / _____
 rejected by Washington / / _____
 pending federal nomination / / _____
 completed Preliminary Information Sheet (PIS) / / _____
 _____ part of NHL district / /
 _____ DOE process / /
 _____ rejected by review board / /
 _____ removed from NR / /
 _____ removed from survey / /
 _____ demolished / /
 _____ nomination on file/never processed / /

12. Number of contributing properties: _____

PROPERTY DESCRIPTION: When other (0) is chosen, enter data on reverse side under category 20 or 21.

13. Construction Date 1900c 14. Alteration Date _____ 15. Architectural style or influence _____

16. Commercial Form — circle appropriate response(s)

- | | | | |
|----------------------------|---------------------------|-------------------|--------------------------|
| A) 2-part commercial block | D) stacked vertical block | G) temple front | J) Central block w/wings |
| B) 1-part commercial block | E) 2-part vertical block | H) vault | K) arched block |
| C) enframed window wall | F) 3-part vertical block | I) enframed block | O) other |

17. DESCRIPTION: Select as many responses as appropriate.

- | | | | |
|--|---|---|---|
| A) HISTORIC CORE SHAPE
rectangular (1) <u>1</u>
square (2)
L (3)
T (4)
U (5)
H (6)
octagonal (7)
irregular (8)
other (0) | D) ROOF SHAPE
gable (end to front) (1)
gable (lateral) (2) <u>2</u>
hip (3)
cross gable (4)
pyramidal (5)
flat (6)
truncated hip (7)
gambrel (8)
mansard (9)
salt box (10)
jerkinhead (11)
gable-on-hip (12)
mono-pitch (14)
not visible (15)
other (0) | F) PORCH ROOF SHAPE
shed (1)
hip (2) <u>2</u>
gable (3)
pedimented gable (4)
flat (5)
engaged (6)
partially engaged (7)
gable-on-hip or shed (8)
engaged porte cochere (9)
other (0) | H) WINDOWS
single (1) <u>1</u>
double (2)
tripartite (3)
grouped (4)
decorative (5)
display (6)
other (0) |
| B) STORIES
1 story (1)
1 1/2 stories (2) <u>2</u>
2 stories (3)
2 1/2 stories (4)
3 stories (5)
other (0) | E) PORCH WIDTH
entrance bay only (1)
over 1 bay, less than full facade (2)
full facade (3) <u>3</u>
facade & left elevation (4)
facade & right elevation (5)
facade & both elevations (6)
other (0) | C) NUMBER OF CHIMNEYS
exterior (1)
interior end (2)
interior (3) <u>3</u>
central (4)
flue (5)
double shouldered (6)
not visible (7)
other (0) | I) PANE CONFIGURATION
traceried (1)
Queen Anne block-glass (2)
Prairie/bungalow/craftsman geometric (3)
not visible (4)
other (0)
<u>2/2</u> / <u> </u> / <u> </u> |
| C) PORCH HEIGHT
1 story (1) <u>1</u>
1 story w/deck (2)
2 or more stories (3)
2 or more with tiers (4)
roofed balcony over 1 story hip/shed (5)
other (0) | | | J) DOORS
single (1) <u>1</u>
double (2)
transom (3)
fanlight (4)
sidelights (5) <u>5</u>
other (0) |

K) CONSTRUCTION METHOD

- masonry (1)
- frame (2)
- log (3)
- steel (4)
- other (0)

L) EXTERIOR WALLS

- weatherboard (1)
- beaded weatherboard (2)
- shiplap (3)
- flushboard (4)
- wood shingle (5)
- stucco (6)
- tabby (7)
- brick (8)
- brick veneer (9)
- stone veneer (10)
- cast-stone (11)
- marble (12)
- asphalt roll (13)
- synthetic siding (14)
- asbestos shingle (15)
- pigmented structural glass (16)
- other (0)

M) PORCH DETAILS

- chamfered posts (1)
- turned posts (2)
- support on pedestals (3)
- columns (4)
- posts (5)
- piers (6)
- pillars (7)
- freestanding posts (8)
- balustrade (9)
- apron wall (10)
- turned balusters (11)
- decorative sawn balusters (12)
- slat balusters (13)
- other sawn/turned work (14)
- insect screening (15)
- porte cochere (16)
- other (0)

N) CHIMNEY MATERIAL

- brick (1)
- stuccoed brick (2)
- stone (3)
- brick & stone (4)
- other (0)

O) ROOF MATERIAL

- composition shingle (1)
- pressed metal shingle (2)
- wood shingle (3)
- slate (4)
- raised seam metal (5)
- other metal (6)
- rolled roofing (7)
- not visible (8)
- tile (9)
- other (0)

P) FOUNDATION

- not visible (1)
- brick pier (2)
- brick pier with fill (3)
- brick (4)
- stuccoed masonry (5)
- stone pier (6)
- stone (7)
- concrete block (8)
- slab construction (9)
- basement (10)
- raised basement (11)
- other (0)

Q) DECORATIVE ELEMENT MATERIAL

- cast iron (1)
- pressed metal (2)
- terra cotta (3)
- granite (4)
- marble (5)
- cast stone (6)
- brick (7)
- wood (8)
- pigmented glass (9)
- stone (10)
- stucco (11)
- other (0)

R) INTERIOR FEATURES (list)

18. HISTORIC OUTBUILDINGS AND STRUCTURES:

- | | | | |
|---------------------------|-------------------|------------------|-------------------|
| none (1) | tenant house (7) | crib (13) | store (19) |
| none visible (2) | other house (8) | smokehouse (14) | windmill (20) |
| garage (3) | office (9) | slave house (15) | chicken coop (21) |
| garage w/ living area (4) | barn (10) | privy (16) | silos (22) |
| shed (5) | tobacco barn (11) | well (17) | washhouse (23) |
| kitchen (6) | dairy (12) | springhouse (18) | root cellar (24) |
| | | | other (0) |

19. SURROUNDINGS: residential (1) residential/commercial (2) commercial (3) rural (4) rural community (5) industrial (6) other (0)

20. ADDITIONAL DESCRIPTIVE COMMENTS: Tall louvered vents at gable ends. Second house on lot is ca. 1935, with front gable roof, gable entry hood, 2/2 sash and aluminum siding; address 116 2nd South Street West.

21. ALTERATIONS Added gingerbread trim.

HISTORICAL INFORMATION

22. Theme(s): _____ 23. Period(s): _____ 24. Important persons: _____
25. Architect(s): _____ Source: _____
26. Builder(s): _____ Source: _____
27. Historical data _____
28. Informant/Bibliography _____

PROGRAM MANAGEMENT

29. Quadrangle name: Summerville 30. Photographs: prints (1) slides (2) negatives (3)
31. Other documentation: survey back-up files (1) National Register files (2) tax act files (3) grant files (4) state historical marker files (5) environmental review files (6) HABS/HAER (7) SCIAA (8) other (0) _____ # _____
32. Recorder name/firm Preservation Consultants: [Signature] 33. Date recorded 3/11/1996

