

Dorchester County
Archives and History Center

K) CONSTRUCTION METHOD

- masonry (1)
- frame (2)
- log (3)
- steel (4)
- other (0)

L) EXTERIOR WALLS

- weatherboard (1)
- beaded weatherboard (2)
- shiplap (3)
- flushboard (4)
- wood shingle (5)
- stucco (6)
- tabby (7)
- brick (8)
- brick veneer (9)
- stone veneer (10)
- cast-stone (11)
- marble (12)
- asphalt roll (13)
- synthetic siding (14)
- asbestos shingle (15)
- pigmented structural glass (16)
- other (0)

M) PORCH DETAILS

- chamfered posts (1)
- turned posts (2)
- supports on pedestals (3)
- columns (4)
- posts (5)
- piers (6)
- pillars (7)
- freestanding posts (8)
- balustrade (9)
- apron wall (10)
- turned balusters (11)
- decorative sawn balusters (12)
- slat balusters (13)
- other sawn/turned work (14)
- insect screening (15)
- porte cochere (16)
- other (0)

N) CHIMNEY MATERIAL

- brick (1)
- stuccoed brick (2)
- stone (3)
- brick & stone (4)
- other (0)

O) ROOF MATERIAL

- composition shingle (1)
- pressed metal shingle (2)
- wood shingle (3)
- slate (4)
- raised seam metal (5)
- other metal (6)
- rolled roofing (7)
- not visible (8)
- tile (9)
- other (0)

P) FOUNDATION

- not visible (1)
- brick pier (2)
- brick pier with fill (3)
- brick (4)
- stuccoed masonry (5)
- stone pier (6)
- stone (7)
- concrete block (8)
- slab construction (9)
- basement (10)
- raised basement (11)
- other (0)

Q) DECORATIVE ELEMENT MATERIAL

- cast iron (1)
- pressed metal (2)
- terra cotta (3)
- granite (4)
- marble (5)
- cast stone (6)
- brick (7)
- wood (8)
- pigmented glass (9)
- stone (10)
- stucco (11)
- other (0)

R) INTERIOR FEATURES (list)

18. HISTORIC OUTBUILDINGS AND STRUCTURES:

- none (1)
- none visible (2)
- garage (3)
- garage w/living area (4)
- shed (5)
- kitchen (6)

- tenant house (7)
- other house (8)
- office (9)
- barn (10)
- tobacco barn (11)
- dairy (12)

- crib (13)
- smokehouse (14)
- slave house (15)
- privy (16)
- well (17)
- springhouse (18)

- store (19)
- windmill (20)
- chicken coop (21)
- silos (22)
- washhouse (23)
- root cellar (24)
- other (0)

19. SURROUNDINGS: residential (1) residential/commercial (2) commercial (3) rural (4) rural community (5) industrial (6) other (0)

20. ADDITIONAL DESCRIPTIVE COMMENTS: Farmhouse with exposed rafter ends and small rear gable wing with shiplap siding. Nearby, at intersection of Mellichamp Rd. and US Highway 78, is a vegetable loading platform alongside the railroad track.

21. ALTERATIONS Porch decking removed. Chimney(s) lost. Shed addition along left elevation.

HISTORICAL INFORMATION

22. Theme(s): _____ **23. Period(s):** _____ **24. Important persons:** _____

25. Architect(s): _____ **Source:** _____

26. Builder(s) _____ **Source:** _____

27. Historical data Employees residence on Drainland, the Clemson/USDA agricultural experiment station between Summerville and Jedburg.

28. Informant/Bibliography _____

PROGRAM MANAGEMENT

29. Quadrangle name: Summerville **30. Photographs:** prints (1) slides (2) negatives (3)

31. Other documentation: survey back-up files (1) National Register files (2) tax act files (3) grant files (4) state historical marker files (5) environmental review files (6) HABS/HAER (7) SCIAA (8) other (0) # _____

32. Recorder name/firm Preservation Consultants: SF **33. Date recorded** 4/2, 1996

