

11. porch details: cantilever porch (18P) normal porch (19) supports on pedestals (20P) columns (20C) posts (20D) piers (20E) pillars (20F) free-standing posts (20G) brackets (20A) screen porch wall (20H) normal balconies (21) cast balconies (22) flat balconies (23) other unenclosed work (24) enclosed and bay (25B) insect screening (25) other (2)

12. windows: single (26) double (26B) paired (26C) tripartite (26D) grouped (26F) decorative (26C) display (26E) other (2)

13. pane configuration: 4/1 / 1 / 1 transomed (27) Sunb-Arm block-glass (28) burglar/airframe panes (29) other (2)

14. doors: single (30) double (30B) transom (30A) sidelight (30C) sidelights (30D) other (2)

15. decorative element: cast iron (31) cast stone (32) terra cotta (33) granite (34) wood (35) pressed metal (36) material: marble (37) other (2)

16. interior features: _____

17. MATERIALS: none (38) none visible (39) granite (39A) granite w/finishing area (39A) steel (39B) stone (39C)

18. MATERIALS: formal house (40) other house (40A) office (40F) bank (40B) tobacco store (40C) dairy (40D) auto (40E) automobile (40G) store house (40I) privy (40H) well (40L) springhouse (40J) store (40K) other (2)

19. MATERIALS: residential (41) residential/commercial (42) commercial (43) rural (44) rural community (45) industrial (46) other (2)

20. additional decorative details: Round arched hood mold over principal entry set in round arched surround with multi-light rounded-arched transom. Secondary entry at right elevation hipped projection has rectangular transom and sidelights.

21. alterations: Modern blinds at windows.

22. HISTORICAL INFORMATION

23. DEDICATED: _____

24. RENOVATED: _____

25. IMPROVED: _____

26. ADDED: _____

27. REMOVED: _____

28. HISTORICAL INFO: Not shown on 1913 Southern map, house appears on 1916 map. 1925 and 1936 City Directories show this as home of William Gilmore Stevens, physician and president of Mount Gallant Dairy Farm, Mount Gallant Ice and Coal Company, and Mount Gallant Flower House. Stevens also served as city commissioner of Rock Hill.

29. PROPERTY INFORMATION

30. PROGRAM NUMBER: Rock Hill

31. PHOTOGRAPHER(S): print Y slides _____ negatives Y

32. OTHER DOCUMENTS: survey back-up files (32P) National Register files (32F) tax and files (32F) grants files (32F) state historical series files (32P) instrumental review files (32F) other (2) _____

33. DESIGNER AND/OR ARCHITECT: DCS, Preservation Consultants, Inc.

34. DATE RECORDED: 08-01-13
BY: _____

35. COMMENTS: _____



IDENTIFICATION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
Survey Field Data/Entry Form
State Historic Preservation Office
100 Boy 11, 565, Columbia, SC 29271
(803)734-6377

COUNTY NUMBER: 11 / 031 / 1 / 1 / 0 / 5 / 6 / 2 / 6 / 7 / 0 / 0
county census block site number
rural place

IDENTIFICATION:



Photo # 1 View of Facade (West Elevation)

Date taken: 88/01/13
Recorded by: D&S, Preservation Systems, Inc.

