

# South Carolina Statewide Survey Site Form

State Historic Preservation Office  
P.O. Box 11668, Columbia, S.C. 29211  
(803) 734-6577

## IDENTIFICATION

1. Control Number W / 91 / 1193 / 424 / 000 1. NR Microfilm Index # \_\_\_\_\_  
county census tract topo street

2. Historic name(s): Huckle, A. M., House; Oakland Presbyterian Church Manse

4. Common name: \_\_\_\_\_

3. Address/location: 303 College Avenue

City Rock Hill Vicinity of \_\_\_\_\_ County York

5. Ownership: private (1) city (2) county (3) state (4) federal (5) 5. Current use(s): single dwelling (1) multi-dwelling (2) other (3)

7. Category: building (1) site (2) structure (3) object (4) 10. Potential: NR (1) NR historic district (2) archaeological (3)

6. Historic use(s): single dwelling (1) multi-dwelling (2) other (3)

11. Name/date: listed individually in National Register \_\_\_\_\_ date \_\_\_\_\_

- listed as part of NR historic district \_\_\_\_\_ Name of district \_\_\_\_\_
- contributing  non-contributing
- listed individually National Historic Landmark \_\_\_\_\_
- determined eligible—owner objection \_\_\_\_\_
- determined NOT eligible \_\_\_\_\_
- deferred by review board \_\_\_\_\_
- reported by Washington \_\_\_\_\_
- pending federal nomination \_\_\_\_\_
- completed Preliminary Information Sheet (PIS) \_\_\_\_\_
- part of NHL district \_\_\_\_\_
- DOE process \_\_\_\_\_
- rejected by review board \_\_\_\_\_
- removed from NR \_\_\_\_\_
- removed from survey \_\_\_\_\_
- demolished \_\_\_\_\_
- nomination on file/never processed \_\_\_\_\_

12. Number of contributing properties: \_\_\_\_\_

## PROPERTY DESCRIPTION: When other (3) is chosen, enter date in roman numerals (see page 20 of 21)

13. Construction Date 1915 14. Alteration Date \_\_\_\_\_ 15. Architectural style or influence \_\_\_\_\_

## 16. Commercial Form — circle appropriate response(s)

- |                            |                          |                   |                           |
|----------------------------|--------------------------|-------------------|---------------------------|
| A) 1-part commercial block | D) marked terminal block | G) simple dorm    | J) Central block entrance |
| B) 1-part commercial block | E) 1-part vertical block | H) vault          | K) marked block           |
| C) enhanced window wall    | F) 1-part vertical block | I) enhanced block | R) other                  |

## 17. DESCRIPTION: Select as many responses as appropriate

- |   |   |   |  |
|---|---|---|--|
| <p><b>A) HISTORIC CORNER SHAPE</b></p> <p>nonangular (1)</p> <p>square (2)</p> <p>L (3)</p> <p>T (4)</p> <p>U (5)</p> <p>H (6)</p> <p>irregular (7)</p> <p>irregular (8)</p> <p>other (9)</p> | <p><b>B) ROOF SHAPE</b></p> <p>gable (eave to eave) (1)</p> <p>gable (battled) (2)</p> <p>copy (3)</p> <p>cross gable (4)</p> <p>pyramidal (5)</p> <p>flat (6)</p> <p>flat-tiled hip (7)</p> <p>gambrel (8)</p> <p>mansard (9)</p> <p>cut line (10)</p> <p>pentagonal (11)</p> <p>golden-hip (12)</p> <p>monopitch (13)</p> <p>non-rivable (14)</p> <p>other (15)</p> | <p><b>F) PORCH ROOF SHAPE</b></p> <p>shed (1)</p> <p>hip (2)</p> <p>gable (3)</p> <p>pentagonal gable (4)</p> <p>flat (5)</p> <p>engaged (6)</p> <p>partially engaged (7)</p> <p>gable-on-top or shed (8)</p> <p>engaged porch cantilever (9)</p> <p>other (10)</p> | <p><b>H) WINDOWS</b></p> <p>single (1)</p> <p>double (2)</p> <p>tripartite (3)</p> <p>grouped (4)</p> <p>decorative (5)</p> <p>single (6)</p> <p>other (7)</p> |
| <p><b>B) STORES</b></p> <p>1 story (1)</p> <p>1 1/2 stories (2)</p> <p>2 (3)</p> <p>3 stories (4)</p> <p>4 stories (5)</p> <p>other (6)</p>   | <p><b>E) PORCH WIDTH</b></p> <p>extensive bay only (1)</p> <p>over 1 bay, less than full (2)</p> <p>full (3)</p> <p>full (4)</p> <p>full (5)</p> <p>gable &amp; left elevation (6)</p> <p>gable &amp; right elevation (7)</p> <p>gable &amp; both elevations (8)</p> <p>other (9)</p>   | <p><b>C) NUMBER OF CHIMNEYS</b></p> <p>—chimney (1)</p> <p>—chimney gnd (2)</p> <p>—chimney (3)</p> <p>—central (4)</p> <p>—flat (5)</p> <p>—double shouldered (6)</p> <p>—non-rivable (7)</p> <p>—other (8)</p>  | <p><b>I) PANE CONFIGURATION</b></p> <p>—divided (1)</p> <p>—Cross Arms (2)</p> <p>—Frame/Transoms/Grilles (3)</p> <p>—non-rivable (4)</p>                      |



**K) CONSTRUCTION METHOD**

- massing (1)
- frame (11)
- log (2)
- steel (6)
- other (5)

**L) EXTERIOR WALLS**

- weatherboard (1)
- boarded weatherboard (2)
- claping (2)
- halfboard (4)
- wood shingle (3)
- stucco (5)
- white (7)
- brick (8)
- brick veneer (5)
- stone veneer (10)
- casement (11)
- marble (12)
- synth. roll (12)
- synthetic siding (12)
- vertical shingle (12)
- papered structural glass (12)
- other (5)

**M) PORCH DETAILS**

- chamfered posts (1)
- turned posts (1)
- appears on porch (1)
- columns (4)
- posts (2)
- piers (8)
- pillars (7)
- freestanding posts (8)
- balustrade (9)
- apron wall (10)
- turned balustr. (11)
- decorative iron balustr. (12)
- slat balustr. (12)
- stone apron/turned work (14)
- iron screening (14)
- posts (14)
- other (14)

**N) CHEMICAL MATERIAL**

- brick (1)
- stuccoed brick (1)
- stone (2)
- brick & stone (1)
- other (3)

**O) ROOF MATERIAL**

- composition shingle (1)
- pressed metal shingle (1)
- wood shingle (5)
- slate (4)
- metal seam metal (4)
- other metal (5)
- rolled roofing (7)
- iron shingle (8)
- other (5)

**P) FOUNDATION**

- iron shingle (1)
- brick pier (1)
- brick pier with sill (2)
- brick (4)
- stuccoed masonry (5)
- stone pier (5)
- stone (7)
- concrete block (8)
- slab construction (9)
- basement (10)
- raised basement (11)
- other (3)

**Q) DECORATIVE ELEMENT MATERIAL**

- cast iron (1)
- pressed metal (2)
- stucco cast (2)
- granite (4)
- marble (4)
- cast stone (5)
- brick (7)
- wood (8)
- papered glass (9)
- stone (10)
- metal (11)

**R) INTERIOR FEATURES (list)**


---



---



---



---

**10. HISTORIC OUTBUILDINGS AND STRUCTURES**

- none (1)
- none stable (2)
- garage (3)
- garage w/bring area (1)
- shed (2)
- hutches (5)

- stables house (1)
- other house (5)
- office (5)
- barn (10)
- warehouse (11)
- dairy (12)

- crib (15)
- stockhouse (16)
- slate house (16)
- porch (16)
- well (17)
- springhouse (18)

- none (19)
- wooded (20)
- chickens coop (21)
- slit (22)
- washhouse (23)
- two celler (24)
- other (5)

**11. SURROUNDINGS residential (1) residential-commercial (2) commercial (5) rural (4) rural community (5) industrial (5) other (5)****12. ADDITIONAL DESCRIPTIVE COMMENTS: Exterior dormer with segmental gable.****13. ALTERATIONS: 1984 porch appears to have been a full-facade, wrapping to both side elevations; only entry section and side porches, ironed screened, remain. Synthetic siding.****HISTORICAL INFORMATION**

14. Theme(s) \_\_\_\_\_ 15. Period(s) \_\_\_\_\_ 16. Important persons \_\_\_\_\_

17. Architect(s) \_\_\_\_\_ Source \_\_\_\_\_

18. Builder(s) \_\_\_\_\_ Source \_\_\_\_\_

19. Historical data: Built for A. W. Buckle, owner of newspaper. Once used as nurse for Oakland Presbyterian Church.20. Informant(s)/Bibliography: City of Rock Hill (August 22, 1988)**PROGRAM MANAGEMENT**21. Quadrangle name: Rock Hill 22. Photographs printed (1) slides (2) tape \_\_\_\_\_

23. Other documentation: survey/locking files (1) National Register files (2) int. int. files (3) grant files (4) state historical markers (5) environmental review files (6) HABS/HAER (7) SCULS (8) other (9) \_\_\_\_\_

24. Recorder name/firm: Preservation Consultants 25. Date recorded: 1/22/88

South Carolina Inventory of Historic Places Survey Form  
CONTINUATION AND PHOTOGRAPHS

Control Number:  $\frac{01}{\text{county}}$  /  $\frac{31}{\text{census}}$  /  $\frac{1175}{\text{parcel \#}}$  /  $\frac{474}{\text{local}}$  /  $\frac{0120}{\text{site \#}}$  /  $\frac{0295}{\text{site \#}}$

Continuation



(Use grid for sketching)




Photo #	Photo Index #	View of	N, S, E, W
<u>1</u>		<u>Facade</u>	<u>E</u>



Date Taken/Recorded by: 3/3/89; photoarchive.com/114844