

## IDENTIFICATION

1. CONTROL NUMBER: 11 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

2. HISTORIC NAME(S): Adams-Barnes House

3. OTHER NAME: Kevin McCarthy House

4. ADDRESS/LOCATION: 222 Marion St.

South Carolina Inventory of Historic Places  
Survey Field Form/State Entry Form  
2020 Historic Preservation Office  
PO Box 11,600, Columbia, SC 29201  
(800) 734-6377

CITY: Rock Hill VICINITY OF: \_\_\_\_\_ COUNTY: York

5. MATERIALS: primary  masonry  masonry  stained  metal  6. CATEGORY: building  stained  structure  object

7. EXTERIOR USE(S):  single dwelling  multi dwelling  other (specify) \_\_\_\_\_

8. EXTERIOR USE(S):  single dwelling  multi dwelling  other (specify) \_\_\_\_\_

9. POTENTIAL:    historic district  archaeological

10. SIGNIFICANCE:  listed individually in National Register  \_\_\_\_\_  
 name \_\_\_\_\_  
 listed as part of a historic district  \_\_\_\_\_  contributing  non contributing  
 name of district \_\_\_\_\_  
 listed individually in National Historic Landmark  \_\_\_\_\_  part of NCL district \_\_\_\_\_  
 determined eligible  other objection \_\_\_\_\_  
 DOE process \_\_\_\_\_  
 determined eligible \_\_\_\_\_  rejected by review board \_\_\_\_\_  
 deferred by Review Board \_\_\_\_\_  removed from list \_\_\_\_\_  
 removed by State Dept \_\_\_\_\_  
 pending federal nomination \_\_\_\_\_  demolished \_\_\_\_\_  
 completed Preliminary Inventory of SHSP (PH) \_\_\_\_\_  nomination in file \_\_\_\_\_  
 never processed

11. NUMBER OF CONTRIBUTING PROPERTIES: \_\_\_\_\_

PROPERTY DESCRIPTION: when other (4) is chosen, enter data under 12. HISTORICAL DESCRIPTION COMMENTS or 13. ALTERNATION

12. CONSTRUCTION DATE: 1910s 13. ALTERNATION DATE: \_\_\_\_\_

14. RESIDENTIAL FORM: \_\_\_\_\_ 15. COMMERCIAL FORM: \_\_\_\_\_ 16. ARCHITECTURAL STYLE OR INFLUENCE: \_\_\_\_\_

17. DESCRIPTION: Select as many responses as appropriate.

a) construction method masonry (M) frame  log (L) steel (S) other (O) \_\_\_\_\_

b) exterior wall material weatherboard (WB) beaded weatherboard (BB) shingle (SP) flushboard (FB) wood shingle  stone (ST) talley (TA) brick (BR) brick veneer (BV) stone veneer (SV) cast stone (CS) terra (TR) asphalt (AS) (SP) synthetic siding (SY) aluminum shingle (AS) pigmented structural glass (PSG) other (O) \_\_\_\_\_

c) historic core shape rectangular  square (S) 4 (4) 1 (1) 2 (2) 3 (3) 4 (4) octagonal (O) irregular (I) other (O) \_\_\_\_\_

d) stories  1 (1) 2 (2) 3 (3) 4+ (4+) other (O) \_\_\_\_\_

e) roof shape gabled to front (FR) gambrel(s) (GB) hip  cross gable (CG) mansard (MS) Flat (FL) truncated hip (TH) gambrel (GB) mansard (MS) salt box (SB) porch roof (PR) front gambrel & side gable (RSG) relationship (RR) not visible (NV) other (O) \_\_\_\_\_

f) roof material composition shingle  pressed metal shingle (PM) wood shingle (WS) slate (SL) built-up (BU) raised iron metal (RM) corrugated metal (CM) rolled roofing (RR) not visible (NV) other (O) \_\_\_\_\_

g) # of chimneys \_\_\_\_\_ exterior (E) \_\_\_\_\_ interior and (IE)  exterior  \_\_\_\_\_ central (CN) \_\_\_\_\_ flat (FL) \_\_\_\_\_ double shoulder (DS) not visible (NV) other (O) \_\_\_\_\_

h) chimney material brick  stuccoed brick (SB) stone (ST) brick & stone (BS) other (O) \_\_\_\_\_

i) foundation not visible (NV) brick pier (BP) brick pier with fill (BPF) brick  stuccoed masonry (SM) stone pier (SP) stone (ST) concrete block (CB) slab construction (SC) basement (BA) raised basement (RB) other (O) \_\_\_\_\_

j) porch height 1 story  1 story without (1W) 2 or more stories (2+) 2 or more with mans. (2M) roofed balcony over 1 story finished (BF) other (O) \_\_\_\_\_

k) porch width entrance bay only (EO) over 1 bay, less than full facade (F) full facade (FF) facade and left elevation (LE) facade and right elevation (RE) facade and both (FB) shed (SD) hip  gable (GB) pedimented gable (PG) flat (FL) engaged (EN) gable-over-hip (GH) other (O) \_\_\_\_\_

l) porch roof shape \_\_\_\_\_



10  
11

13. porch details: clustered posts (C6P) turned posts (C7P) supports on pedestals (C8P) columns (C9A) posts (C9B) piers (C9C) pilasters (C9L) transoms (C9T) brackets (C9A) masonry apron wall (C9M)  
turned balustrade (C9D) cast balustrade (C9E) steel balustrade (C9F) other unclassified (C9G) (C9H)  
enclosed and bay (C9I) braced screening (C9J) other (C9K)
14. windows: single (C6A) double (C6B) paired (C6C) tripartite (C6D) grouped (C6E) decorative (C6F) display (C6H) other (C6I)
15. pane configuration: single (C6A) transoms (C6B) leaded and block glass (C6C) tungsten/strontium glass (C6D) (C6E) other (C6F)
16. doors: single (C6A) double (C6B) transoms (C6C) fanlight (C6D) sidelights (C6E) other (C6F)
17. decorative elements: cast iron (C6I) cast stone (C6J) terra cotta (C6K) grout (C6L) wood (C6M) pressed metal (C6N)  
marble (C6O) other (C6P)
18. interior features: \_\_\_\_\_
19. OUTBUILDINGS: none (C7A) none visible (C7B) garage (C7C) garage w/living area (C7D) shed (C7E) kitchen (C7F)  
laundry (C7G) other house (C7H) office (C7I) barn (C7J) tennis court (C7K) dairy (C7L) utility (C7M)  
workshop (C7N) stone house (C7O) privy (C7P) well (C7Q) springhouse (C7R) store (C7S) other (C7T)
20. SURROUNDING: residential (C8A) residential/commercial (C8B) commercial (C8C) rural (C8D) rural community (C8E)  
industrial (C8F) other (C8G)

21. ADDITIONAL DESCRIPTIVE COMMENTS: no other wood shingle apron wall; porch pillars clad in wood shingles.  
Pedimented front gable with clerestory window; rock facing in gable end. Pedimented left  
gable with double lowered attic vents. Slight hipped projection at right elevation. Rear  
hipped extension. Windows are double, with diamond-paned transoms/l muntins.

22. A REMARK: Hipped rear addition with shingle siding

HISTORICAL INFORMATION

23. PHOTOGRAPHS: \_\_\_\_\_
24. PERSPECTIVES: \_\_\_\_\_
25. SPECIAL FEATURES: \_\_\_\_\_
26. ARCHITECTURE: \_\_\_\_\_ SOURCE: \_\_\_\_\_
27. MATERIALS: \_\_\_\_\_ SOURCE: \_\_\_\_\_
28. HISTORICAL DATA: Area not included on 1960 Sanborn map; house appears on 1916 and 1926 maps.  
1916 Bates Book shows this as home of Mrs. M. H. Adams; City Directories show Frank Barnes  
living here in 1925 and 1926. Has also been occupied by members of the Colbert and McCarthy  
families.
29. AGENCY/ORGANIZATION: Mid-Town Preservation Association

PROGRAM INFORMATION

30. IDENTIFIABLE NAME: Rock Hill No. PHOTOGRAPHS/TILES: prints Y slides \_\_\_\_\_ negatives Y
31. OTHER DOCUMENTATION: survey back-up files (C9P) national register files (C9Q) tax and files (C9R) grants files (C9S)  
state historical marker files (C9T) environmental review files (C9U) other (C9V) \_\_\_\_\_
32. RECORDS MAINTAINED: DBS, Preservation Consultants, Inc.
33. DATE RECORDED: 3/21/08
34. COMMENTS: \_\_\_\_\_



EXPLANATION OF PHOTOGRAPHS

Each card in this category of slides is placed  
under the appropriate slide mount  
slide frame in numerical order  
and the number of slides in the  
category is noted.

DATE TAKEN: 1/10/81 11:30 AM 1/10/81 11:30 AM 1/10/81 11:30 AM  
SLIDE NO. 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

DESCRIPTION

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Slide

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Slide

EXPOSURE (WATER MARK)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Slide No. 810019

Prepared by: R&A Preservation Consultants, Inc.

