

IDENTIFICATION

South Carolina Inventory of Historic Places
 Survey Field Form/Field Entry Form
 State Historic Preservation Office
 PO Box 17,000, Columbia, SC 29211
 (803) 726-0377

1. SURVEY NUMBER: U 191 / 11195 / 024 / 224

country census serial site number
 road plan

2. SURVEY NAME: Cleveland K. Schurer House

3. OTHER NAME: _____

4. ADDRESS/LOCATION: 375 College Ave.city, Rock Hill vicinity of: _____ county, York5. CURRENT USE: private other occupied storage Federal & CURRENT BUILDING STAFFED UNSTAFFED OCCUPIED7. HISTORIC USE(S): single dwelling multi dwelling other (specify) _____8. CURRENT USE(S): single dwelling multi dwelling other (specify) _____9. POTENTIAL: AH NH historic district archaeological10. EVALUATION: listed individually in national register _____

_____ listed as part of a historic district contributing non-contributing

name of district: _____

_____ listed individually in National Historic Landmarks part of N.H. district _____

_____ designated a historic site - name of district _____

_____ still process _____

_____ recommended for listing rejected by review board _____

_____ deferred by review board removed from list _____

_____ rejected by commission removed from survey _____

_____ pending Federal nomination demolished _____

_____ supplied first primary information (SHS) (FIS) nomination on file _____

_____ never processed

11. NUMBER OF CONTRIBUTION FEATURES: _____

PROPERTY DESCRIPTION: other (if) is chosen, enter data under ADDITIONAL DESCRIPTION COMMENTS or ATTENTION12. CONSTRUCTION DATE: 1915c

13. ALTERNATE DATE: _____

14. MATERIALS FROM: _____

15. COMMERCIAL FROM: _____

16. ARCHITECTURAL STYLE OR INFLUENCE: _____

17. DESCRIPTION: select as many responses as appropriate.

a) construction method masonry (250) brick (150) log (180) steel (200) other (2)

b) exterior wall masonry (250) plastered masonry (250) shiplap (200) flushboard (250) wood shingle (200) stone (250)

_____ stucco (200) brick (200) brick veneer (200) stone veneer (200) cast-stone (200) terra (200)

_____ asphalt roll (180) synthetic siding (200) asbestos shingle (200) pigmented structural glass (200) other (2)

c) historic core shape rectangular (100) square (2) L (1) T (1) U (2) H (2) irregular (1) other (2)

d) stories 1 1 1/2 2 2 1/2 3 4+ other (2)

e) roof shape gabled to front (200) gambrel (200) hip (200) cross gable (200) pyramidal (200)

_____ flat (200) truncated hip (200) gambrel (200) mansard (200) salt box (200) arched (200)

_____ front gable/hip & wing (200) gable-in-hip (200) not visible (200) other (2)

f) roof material composition shingle (100) pressed metal shingle (200) wood shingle (200) slate (200) built-up (200)

_____ raised oak bark (200) corrugated metal (200) rolled roofing (200) not visible (200) other (2)

g) # of chimneys _____ exterior (20) _____ interior and (20) _____ interior (20) _____ tower (20)

_____ double (20) not visible (20) other (2)

h) chimney material brick (20) stucco brick (20) stone (20) brick & stone (20) other (2)

i) foundation not visible (20) brick pier (20) brick pier with fill (20) brick (20) stucco masonry (20)

_____ stone pier (20) stone (20) concrete block (20) slab construction (20) basement (20)

_____ raised basement (20) other (2)

j) porch height 1 story (10) 1 story with (20) 2 or more stories (20) 2 or more with tiers (2)

_____ roofed balcony over 1 story (10) other (2)

k) porch width entrance bay only (20) over 1 bay, less than full, facade (20) full facade (10)

_____ full facade and left (10) full facade and right elevation (20) facade and both (2)

l) porch roof shape shed (20) hip (20) gable (20) gambrel gable (20) flat (20) wrapped (20)

_____ gable-in-hip (20) other (2)



17. porch details: sheltered porch (CMP) turned porch (TP) supports or posts (CSP) columns (COL) posts (PO) planters (PL) pillars (PI) freestanding porch (FP) balconies (BP) heavy stone wall (HW) turned balustrade (TB) cast balustrade (CB) steel balustrade (SB) other balustrade (OB) other non-toured work (NT) enclosed end bay (EB) insect screening (IS) other (O)

18. window: single (S) double (DL) paired (PD) triangular (TF) grouped (GP) decorative (DC) display (DI) other (O)

19. pane configuration: 1 1 triangular (TR) flush area block glass (AG) suspended/offset pane (OP) other (O)

20. door: single (S) double (DL) transom (TB) fanlight (FL) sidelights (SL) other (O)

21. decorative element: cast iron (CI) cast stone (CS) terra cotta (TC) granite (GR) wood (W) pressed metal (PM) marble (M) other (O)

22. interior features: _____

23. HISTORIC: none (N) none visible (NV) garage (GA) garage utility area (GUA) shed (SH) kitchen (KF)

24. ATTACHED: front house (FH) other house (OH) office (OF) barn (BN) tobacco barn (TB) dairy (DA) orio (OR) workshop (WO) store house (SH) privy (PV) well (WL) springhouse (SP) store (ST) other (O)

25. SURROUNDING: residential (R) residential/commercial (RC) commercial (C) rural (RU) rural community (RCOM) industrial (IND) other (O)

26. ADDITIONAL DESCRIPTIVE COMMENTS: Porch deck intersects with deck of left elevation hipped porch, which has exposed rafter ends. Shed dormer with grouped RG windows.

27. ALTERNATES: Aluminum storm doors and windows.

TECHNICAL INFORMATION

28. PHOTO(S): _____

29. VIDEO(S): _____

30. EXISTING RECORD(S): _____

31. ARCHITECT(S): _____ SOURCE: _____

32. ENGINEER(S): _____ SOURCE: _____

33. REVISION DATA: Area not included on 1910 Sanborn map; house appears on 1924 map. Said to have been residence of Knicker editor C.K. Schwab in the 1910s.

34. RESEARCH/FILE SOURCE: Old-Town Preservation Association

PROJECT SUMMARY

35. DRAINAGE: Rock Hill 36. PHOTOGRAPHY: prints Y slides _____ negative Y

37. OTHER DOCUMENTATION: survey back-up files (S) National Register files (NF) tax lot files (TF) photo files (PF) state historical marker files (MF) environmental review files (ER) other (O) _____

38. RESEARCHER(S): DES, Preservation Consultants, Inc.

39. DATE RECORDED: 11/11/08
year month day

40. COMMENTS: _____



DESCRIPTION AND COMMENTS

State Historic Inventory of Historic Places
Survey Form Number 1000-100
This form is intended for use
in the U.S. States, the District
of Columbia

UNIVERSITY OF CALIFORNIA
HERNANDEZ HOUSE
1000-100

DATE OF VISIT



NAME

NO.

1000-100

Date taken: 11/1/68

Recorded by: J. Preservation Consultants

