

## IDENTIFICATION

South Carolina Inventory of Historic Places  
Survey Field Data/Check Entry Form  
State Historic Preservation Office  
PO Box 16,084, Columbia, SC 29211  
(803) 756-8577

1. CONTROL NUMBER: 12 / 34 / 1 / 1 / 2 / 2 / 4 / 2 / 4 / 3 / 6 / 0  
county record date after date  
reel place

2. REPORT NUMBER: Camford-Blackmon House

3. OTHER NAME:

4. ADDRESS/LOCATION: 363 East Main St.

CITY: Rock Hill VICINITY OF: \_\_\_\_\_ COUNTY: York

5. OWNER(S): private(s) city(s) county(s) state(s) federal(?) EDUCATION building(?) other structural(s) object(s)

6. CURRENT USE(S): 1 single dwelling 2 multi dwelling other use(s) \_\_\_\_\_

7. CURRENT OBJECT: 1 single dwelling 2 multi dwelling other object \_\_\_\_\_

8. POTENTIAL: 1 2 3 historic district archaeological \_\_\_\_\_

9. EVALUATION: 1 listed individually in National Register \_\_\_\_\_

2 listed as part of the National Register \_\_\_\_\_ CONTINUING 3 not continuing  
name of district \_\_\_\_\_

4 listed individually National Historic Landmark \_\_\_\_\_ part of N.H. district \_\_\_\_\_

5 determined eligible - under objection \_\_\_\_\_

6 not process \_\_\_\_\_

7 determined not eligible \_\_\_\_\_ rejected by review board \_\_\_\_\_

8 deferred by review board \_\_\_\_\_ removed from list \_\_\_\_\_

9 rejected by local agency \_\_\_\_\_ removed from survey \_\_\_\_\_

10 pending Federal review \_\_\_\_\_ completed \_\_\_\_\_

11 completed preliminary information (SHP) (FIS) \_\_\_\_\_ rejected by FHWA \_\_\_\_\_  
review processed \_\_\_\_\_

11. NAME OF CONTINUING PROPRIETOR: \_\_\_\_\_

PROPERTY DESCRIPTION: check other (X) to choose, enter data under 1 ADDITIONAL DESCRIPTION NUMBER or 2 ALTERNATION

12. CONSTRUCTION DATE: 1900s 13. ALTERNATION DATE: \_\_\_\_\_

14. VERGULAR FORM: \_\_\_\_\_ 15. COMMERCIAL FORM: \_\_\_\_\_ 16. ARCHITECTURAL STYLE OR INFLUENCE: \_\_\_\_\_

17. DESCRIPTION: Select as many responses as appropriate.

a) construction method masonry (M) frame (F) log (L) steel (S) other (O)

b) exterior wall weatherboard (WB) beaded weatherboard (BWB) shingle (SH) flushboard (FB) wood shingle (WS) stone (ST)  
metal (ME) brick (BR) brick veneer (BVR) stone veneer (SV) cast stone (CS) marble (MR)  
asphalt roll (AR) synthetic siding (SY) asbestos shingle (AS) pigmented structural glass (PSG) other (O)

c) historic core shape rectangular (R) square (SQ) L, G, T, U, S, O, P, Q, W, X, Y, Z, other (O)

d) stories 1 1 1/2 2 2 1/2 3 4+ other (O)

e) roof shape gabled to front (GF) gambrel/curved (GC) hip (HP) cross gable (CX) gambrel (GR)  
flat (FL) truncated hip (TH) gambrel (GM) mansard (MA) salt box (SB) porch/lean (PL) front gable/hip & gable, other, other/hip (OH) not visible (NV) other (O)

f) roof material composition shingle (CS) pressed metal shingle (PMS) wood shingle (WS) slate (SL) built-up (BU)  
rolled zinc metal (RZM) corrugated metal (CM) rolled roofing (RR) not visible (NV) other (O)

g) # of chimneys exterior (EX) interior and (IA) interior (IN) central (CN) five (FV)  
double chimney (DC) not visible (NV) other (O)

h) chimney material brick (BR) stuccoed brick (SB) stone (ST) stone & stone (SS) other (O)

i) foundation not visible (NV) brick pier (BP) brick pier with (P) (BPP) brick (BR) stepped masonry (SM)  
stone pier (SP) stone (ST) concrete block (CB) slab construction (SL) basement (BS)  
raised basement (RB) other (O)

j) porch height 1 story (1S) 1 story wide (1W) 2 or more stories (2+) 2 or more with tiers (2T)  
raked balcony over 1 story high/steep (RH) other (O)

k) porch width entrance bay only (EO) over 1 bay, less than full facade (LF) full facade (FF) g  
facade and left elevation (FL) facade and right elevation (FR) facade and both (F)

l) porch roof shape shed (SD) hip (HP) gable (GB) perforated gable (PG) flat (FL) engaged (EN)  
pediment (PE) other (O)



10. porch details: cantilevered porch (CP1) turned porch (TP) supports on pedestals (SP) columns (CC1) posts (PO) piers (PI) pilings (Pi) transoms (TR) balustrade (BAL) masonry apron wall (MAW) turned balustrade (TB) cast balustrade (CB) cast balustrade (SL) cast balustrade with (LW) enclosed end bay (CEB) fence screening (CS) other (C)
11. window: single (S1) double (D1) paired (PR) tripartite (TR) grouped (GR) decorative (DC) display (DI) other (O)
12. pane configuration: L L L tracery (TR) flush pane (FP) glass (GL) single-pane/flush pane (SPF) other (O)
13. pane: single (S1) double (D1) tripartite (TR) tripartite (TR) sidelights (SL) other (O)
14. decorative element: cast iron (CI) cast stone (CS) terra cotta (TC) granite (GR) wood (WO) pressed metal (PM) material: marble (MR) other (O)
15. interior features:

16. historic: none (N) non-viable (NV) garage (GAR) garage w/living area (GLA) shed (SD) kitchen (KT)
17. bathroom: cement base (CB) other base (OB) office (OF) bare (BR) tubless base (TBR) entry (EN) entry (EN)
18. bathroom: entrance (ER) glass house (GLH) entry (EV) wall (WL) springhouse (SP) store (ST) other (O)
19. surrounding: residential (R) residential/commercial (RC) commercial (C) rural (RU) rural community (CR) industrial (IR) other (O)

20. additional descriptive comments: Pedimented front gable projection over cutaway bay; half-round lowered sills west in gable end; applied pebble surface in gable end. Focal windows are tracery/1; paired tracery windows at first and second levels of facade. Historic wood and glass entry door is surround. Bracketed awnes at front gable. Hipped projection at rear of left elevation.

21. a. materials: Synthetic siding and storm windows, after 1981; shed addition at rear.

HISTORICAL INFORMATION

22. THRU(1): \_\_\_\_\_
23. FROM(1): \_\_\_\_\_
24. IMPORTANT PERSONS(1): \_\_\_\_\_
25. ARCHITECT(1): Starr, Julian SOURCE: tradition
26. BUILDER(1): \_\_\_\_\_ SOURCE: \_\_\_\_\_
27. HISTORICAL DATA: See Site #533 for earlier house on lot. Buil; for E. W. Crawford; sold to Mrs. T. M. Mygerson, then to Dr. W. R. Blackmon in 1921. Dr. Blackmon is shown as living here in the 1929 and 1936 City Directories; the 1914 Rock Hill Rates Book lists E. W. Crawford at this location. Crawford had founded The E. W. Crawford Company Department Store.
28. CURRENT OCCUPANTS: Mrs. Mackay J. Norman, 361 West Main St.

FORMS COMPLETED

29. SURVEYOR'S CODE: Rock Hill 30. PHOTOGRAPHED: prints, Y slides \_\_\_\_\_ negative Y
31. OTHER DOCUMENTATION: survey back-up files (S1) National Register files (NR) tax act files (TA) grants files (GR) state historical marker files (SH) environmental review files (ER) other (O)
32. RECORDS MAINTENANCE: RHS, Preservation Consultants, Inc.
33. DATE RECORDED: 3/11/10
34. COMMENTS:



DESCRIPTION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places  
 Survey Field Form/Status Entry Form  
 State Historic Preservation Office  
 PO Box 11,668, Columbia, SC 29211  
 (803)734-8077

DATE: 11/9/11 11:19 AM 11/9/11  
county state city site name

CONTINUED:

---



---



---



---



---



---



---



ROLL #

1  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SLIDE

PHOTO (AND SLID)  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Base taken whole  
 Recorded by TRK, PRESERVATION

