

IDENTIFICATION

South Carolina Inventory of Historic Places
 Bureau Field Form/State Entry Form
 State Historic Preservation Office
 40 Lee Street, Columbia, SC 29201
 (803) 734-6577

1. CONTROL NUMBER: 01/91/11/95/1024/411
county census entry site number

2. REPORT NUMBER: Gettys Society

3. OTHER NOS.:

4. ADDRESS/LOCATION: 411 Hampton St.

city: Rock Hill vicinity of: _____ county: York

5. GENERALITY primary city county state federal A. FEDERAL: building artifact structural object

7. HISTORIC USE(S): single dwelling multi dwelling other use(s) SECURITY STORE

8. CURRENT USE(S): single dwelling multi dwelling other use(s) SECURITY

9. POTENTIAL: no no historic district archaeological

10. STATUS/DATE: listed individually in National Register no no

listed as part of an historic district no no pending not contributing
(name of district)

listed individually National Historic Landmark no no part of NCL district no

determined eligible - owner objection no no

not eligible no no

determined not eligible no no rejected by review board no

deferred by review board no no removed from list no

removed by legislation no no removed from survey no

pending Federal report number no no cancelled no

expedited preliminary information (6600) (710) no no reinstated on file no

never processed

11. NUMBER OF CONTRIBUTING PROPERTIES: _____

PROPERTY DESCRIPTION: when other (4) is chosen, enter data under 2 ADDITIONAL DESCRIPTION or 11 ALTERNATE

12. CONSTRUCTION DATE: 1910c 13. ALTERATION DATE: _____

14. VEHICULAR FORM: _____ 15. COMMERCIAL FORM: _____ 16. ARCHITECTURAL STYLE OR INFLUENCE: _____

17. DESCRIPTION: listed in entry response as appropriate.

a) construction method masonry (240) frame log (200) stone (260) other (2)

b) exterior wall material weatherboard beaded weatherboard (240) shingles (260) flushboard (260) wood shingles (260) stucco (21) table (240) brick (260) brick veneer (260) stone veneer (260) cast-stone (260) marble (240) asphalt (21) (260) synthetic staling (270) asbestos shingles (240) pigmented structural glass (260) other (2)

c) historic core shape rectangular square (2) L-shape (1) T-shape (1) U-shape (1) octagonal (2) irregular (1) other (2)

d) stories 5 1 1/2 2 2 1/2 3 4+ other (2)

e) roof shape gabled to front gabled/central (260) hip (260) cross gable (260) pyramidal (260) flat (24) truncated hip (260) gambrel (240) mansard (260) salt box (260) arch/steep (260) front gambrel-hip (260) gambrel-hip (260) red visible (260) other (2)

f) roof material composition shingles (220) pressed metal shingles (260) wood shingles (240) slate (260) built-up (24) rolled steel metal corrugated metal (260) rolled roofing (260) red visible (260) other (2)

g) # of chimneys exterior (2) interior and (260) interior (260) central (260) flue double chimneyed (2) red visible (26) other (2)

h) chimney material brick shrouded brick (26) stone (27) brick & stone (26) other (2)

i) foundation no visible (26) brick pier (26) brick pier with fill (26) brick stone/brick masonry (26) stone pier (27) stone (26) concrete block (26) slab construction (240) basement (240) raised basement (240) other (2)

j) porch height 1 story (26) 1 story without (240) 2 or more stories (2) 2 or more with clear roofed balcony over 1 story (260) other (2)

k) porch width entrance bay only (240) over 1 bay, less than full facade (2) full facade (2) facade and left elevation (26) facade and right elevation (26) facade and bay

l) porch roof shape shed (26) hip (26) gable (240) gambrelled gable (260) flat (26) engaged (240) gable-on-gable or shed (240) other (2)



10

11

10. porch details: clustered posts (10A) turned posts (11) supports on pedestals (12A) columns (12L) posts (13) piers (14) pilasters (15) free-standing posts (16) balustrade (16A) masonry apron wall (16B) turned balustrade (17) cast balustrade (18) cast balustrade (19) other cast/formed work (20) enclosed and bay (20A) insect screening (21) other (2)
11. window: single (30L) double (30R) paired (30C) tripartite (31) grouped (32) decorative (33) sliding (34) other (2)
12. pane configuration: 1/2 1/2 inserted (35) Queen Anne black glass (36) burgundy/strawberry pattern (37) other (38)
13. sash: single (40) double (40L) transom (41A) fanlight (41L) sidelights (42) other (2)
14. decorative element: cast iron (51) cast stone (52) terra cotta (53) granite (54) wood (55) pressed metal (56) material: marble (60) other (2)

15. interior features:

16. exterior: none (71) none visible (72) garage (73A) garage w/entry area (73B) shed (74) kitchen (75)
17. entrance: front house (76) other house (77) office (78) barn (79A) carriage barn (79B) dairy (80A) milk (80B)
18. enclosure: greenhouse (81) slave house (81A) privy (82A) well (82B) springhouse (83) store (84) other (2)
19. enclosure: residential (91) residential/commercial (91C) commercial (2) rural (92) rural community (93) industrial (94) other (2)

15. ADDITIONAL DESCRIPTIVE COMMENTS: as other: 6-light windows. Storefront has recessed entry flanked 6-light storefront windows. Facade with stepped parapet of shiplap siding, with lowered angle vent. Exposed rafters over. Shed projection at right elevation with single window; secondary entry at rear of left elevation. No window openings at left elevation.

16. ALTERATIONS: Projection at right elevation; lowered vent

HISTORICAL INFORMATION

20. THING(S): _____
21. ADDRESS: _____
22. STREET AND NUMBER: _____
23. ARCHITECT(S): _____ SOURCE: _____
24. BUILDERS: _____ SOURCE: _____
25. HISTORICAL DATA: Area not included on 1910 Sanborn map, building appears on 1916 and 1926 maps. 1916 Bates Book shows it owned by Mrs. L. L. Biggers, rented by F. T. Cox; vacant in 1925; 1926 City Directory lists it as Gettys Grocery (See Site #488 for Gettys House).

26. INFORMATION SOURCE:

- RECORD MANAGEMENT
27. SURVEYOR'S NAME: Rock Hill 28. PHOTOGRAPH(S): print Y slides _____ negatives Y
29. OTHER DOCUMENTATION: survey field-notes files (1) National Register files (2) Tax map files (3) _____
30. HISTORICAL CENTER FILES (4) environmental review files (5) other (2) _____
31. RECORDS MAINTENANCE: DCD, Preservation Consultants, Inc.

32. DATE RECORDED: 07/12/15
33. COMMENTS: see record log



