

10. porch details: cantilever posts (18P) turned posts (19P) supports on pedestals (20P) columns (20L) posts (20S)
 posts (20T) pillars (20L) freestanding posts (20F) brackets (20A) memory open wall (20M)
 turned balustrade (20) cast balustrade (20) cast balustrade (20) other cast/turned cast (20T)
 enclosed and bay (20B) insect screening (20) other (2)
11. windows: single (21) double (22L) picture (22R) tripartite (23) grouped (24P) decorative (22D) 2-light (22B) other (2)
12. pane configuration: 4/4 6/6 triangular (25) flush area double glass (26) burglar/fire/other protection (22D) other (2)
13. pane: single (27) double (28L) transom (28R) full-light (27L) sidelight (27B) other (2)
14. decorative element: cast iron (31) cast stone (32) terra cotta (33) granite (34) wood (35) pressed metal (36)
 marble (37) other (2)
15. interior features: _____

16. exterior: none (41) none visible (42) garage (43) garage w/living area (44) shed (45) window (47)
 OTHER (46): covered house (74) other house (28) office (24F) barn (28B) tobacco barn (78B) dairy (24D) 1/2 (28B)
 automobile (28) slave house (24L) privy (24V) well (24E) other (2)
17. surrounding: residential (51) residential/commercial (52) commercial (53) rural (54) rural community (55)
 industrial (56) other (2)

18. additional descriptive comment: facade window 6/6 flanked by 4/4, 8/6 windows in side gable pro-
jections, 4/4 elsewhere, 4-light gable windows.

19. additional comment: Half-tipped shed attachment attached to rear bay of right elevation. 1X1 bay
porch addition with insect screening at left elevation. Shed trill at front sill.

HISTORICAL INFORMATION

20. ADDRESS: _____
21. PARCELS: _____
22. INTERIOR PARCELS: _____
23. ARCHITECT: _____ SOURCE: _____
24. BUILDERS: _____ SOURCE: _____
25. HISTORICAL DATA: Area not included in 1905 Sanborn map. House appears on 1910 and later maps.
1934 Bates Book lists F. B. Johnston as owner of this and three neighboring houses. Occupied
in 1915 by D. Harley Gaudin, mechanic with Roddy-Hald Federal Company.

26. INFORMATION SOURCE: _____

PHOTO DOCUMENT

27. NEGATIVE NO.: Rock Hill M. PHOTOGRAPHIC: print Y slide _____ negative Y
28. OTHER DOCUMENTATION: survey/lotting files (29) national register files (30P) easement files (30S) grant files (30T)
 state historical marker files (30V) environmental review files (30W) other (2)
29. RECORDS COMPANY: DES, Preservation Consultants, Inc.
30. DATE RECORDED: 8/21/13
31. COMMENTS: _____



