

IDENTIFICATION

South Carolina Inventory of Historic Places
Survey Field Form/In Situ Survey Form
State Historic Preservation Office
PO Box 11,566, Columbia, SC 29201
(800) 754-0077

1. CONTROL NUMBER: SC 11 33 3 / 4 2 4 - 3 2 0
county district county
serial place site number

2. HISTORIC NAME(S): Albert Whiteside House

3. OTHER NAME:

4. ADDRESS/LOCATION: 421 Park Ave.

CITY: Rock Hill VICINITY OF: COUNTY: York

5. APPLICABLE FEDERAL OR STATE AGENCY(IES) (CHECK ALL THAT APPLY): FEDERAL (F) STATE (S) LOCAL (L) OTHER (O) STRUCTURED OBJECTIVE (SO)

7. HISTORIC USE(S): Single dwelling multi dwelling other use(s)

8. CURRENT USE(S): Single dwelling multi dwelling other use(s) NONE

9. POTENTIAL: is is historic district archaeological

10. STATUS/DATE: listed individually in National Register is is

listed on (COPY OF) in Historic district is is contributing is contributing

name of district

listed individually in National Historic Landmark is is part of N.H. district

national historic is is is

landmark

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

is

rejected by review board

removed from list

removed from survey

status revised

reinstated on NHR

never processed

11. NAME OF CONTRIBUTOR PROPERTY:

PROPERTY DESCRIPTION: when other (X) is shown, enter date under IS, ORIGINAL, RESTRICTION, CONVEY or IS, ALIENATION

12. RESTRICTION DATE: 1900s

13. ALIENATION DATE:

14. VEHICULAR FORM: IS, CONCRETE FORM

15. ARCHITECTURAL STYLE (OR INSPIRED):

17. DESCRIPTION: taken as best response or appropriate.

a) construction method: masonry (M); frame (F); log (L); steel (S); other (O)

b) exterior wall: weatherboard (WB) board weatherboard (BB) shingle (SH) flushboard (FB) wood shingle (WS) stone (ST)

material:

clay (CL) brick (BR) brick veneer (BV) stone veneer (SV) cast-stone (CS) terra (TR)

split rail (SR) synthetic siding (SY) asbestos shingle (AS) pigmented structural glass (PSG) other (O)

c) historic core shape: rectangular (R) square (SQ) T CT) U CT) R CT) octagonal (O) irregular (I) other (O)

d) stories: 1 1 1/2 2 2 1/2 3 4+ other (O)

e) roof shape: gabled to front (FR) gambrel (G) hip (HP) cross gable (CG) gambrel (GR)

flat (FL) truncated hip (TH) gambrel (GA) mansard (MA) salt box (SB) gambrel (GB)

front gambrel hip & wing (FG) gambrel-hip (GH) not visible (NV) other (O)

f) roof material: composition shingle (CS) pressed metal shingle (PM) wood shingle (WS) slate (SL) roofing (RT)

rolled steel metal (RM) corrugated metal (CM) rolled roofing (RR) not visible (NV) other (O)

g) # of chimneys: exterior (EX) interior and (IO) interior (IN) chimney (CH) double (DB)

double attached (DA) not visible (NV) other (O)

h) chimney material: brick (BR) glazed brick (GB) stone (ST) brick & stone (BS) other (O)

i) foundation: not visible (NV) brick pier (BP) brick pier with fill (BPF) brick (BR) stucco masonry (SM)

stone pier (SP) stone (ST) concrete block (CB) slab construction (SC) basement (BA)

raised basement (RB) other (O)

j) porch height: 1 story (1S) 1 story without (1SW) 2 or more stories (2+) 2 or more with stairs &

ramped balcony over 1 story (1SB) other (O)

k) porch width: entrance bay only (EO) over 1 bay, less than full facade (B) full facade (FF)

facade and left elevation (LE) facade and right elevation (RE) facade and both

shed (SD) hip (HP) gable (GA) pedimented gable (PG) flat (FL) engaged (EG)

gable or hip (GH) other (O)



12. porch details: castled posts (2P) turned posts (2P) supports on pedestals (2P) columns (2L) posts (2P) pilars (2L) pillars (2L) freestanding posts (2P) balustrade (2A) masonry apron wall (2A) turned balustrade (2L) cast balustrade (2L) flat balustrade (2L) other balustrade (2L) other unclassified work (2/1) enclosed and bay (2B) raised screening (11) other (2)
13. windows: single (2A) double (2L) paired (2B) tripartite (2P) grouped (2P) decorative (2B) display (2L) other (2)
14. pane configuration: 2/2 2/1 framed (2L) flush area black glass (2A) triangular/trapezoidal geometric (2B) other (2)
15. glazing: single (2A) double (2L) transom (2B) fanlight (2A) sidelights (2A) other (2)
16. decorative element: cast iron (2) cast stone (2) terra cotta (2) granite (2) wood (2) pressed metal (2) metal (2) other (2)
17. interior features: Historic stair w/ metal post; doors w/transoms; picture rail, cornices, mantels
18. HISTORY: none (2) none visible (2) garage (2A) garage w/living area (2L) shed (2B) strobes (2P)
19. OUTBUILDINGS: tenant house (2L) other house (2B) office (2P) barn (2B) tobacco barn (2B) dairy (2A) 2/1 (2B) warehouse (2B) slave house (2L) jail (2P) well (2L) springhouse (2P) store (2B) other (2)
20. SURROUNDINGS: residential (2) residential/commercial (2/2) commercial (2) rural (2B) rural community (2B) industrial (2B) other (2)

21. ADDITIONAL DESCRIPTIVE COMMENTS: Wood columns on brick pedestals, paired at steps. Stained glass fanlight. Second level deck access door with tracery stained glass transom and sidelights. Hipped dormer with three 12/3 windows. Patterned composition roof. Rear hipped and gable extensions. Triangular covered attic vent in left gable projection. Historic window blinds remain.

22. ALTERNATES: Windows boarded over. Porch deck railing lost. Rear porch enclosed. Brick infill at brick pier foundation at rear.
with cast cornices; replacement ceiling.

23. HISTORICAL INFORMATION

23.1. THROTTLE: _____

23.2. PERIOD(S): _____

23.3. IMPORTANT PERSON(S): _____

23.4. ARCHITECT(S): _____ SOURCE: _____

23.5. BUILDING(S): _____ SOURCE: _____

24. HISTORICAL INFO: Area not on 1910 Sanborn map; house appears on 1916 map. 1914 Bates Book and 1925 City Directory show it as home of Albert N. Whiteside, textile engineer with Victoria Mill #1.

25. INFORMATION SOURCES

25.1. PREVIOUS DOCUMENTS: Rock Mill 25.2. PHOTOGRAPHIC(S): prints Y slides _____ negatives Y

25.3. OTHER DOCUMENTATION: survey back-up files (2P) National Register files (2P) tax and files (2A) grants files (2P) state historical marker files (2P) environmental review files (2P) other (2)

25.4. NUMBER AND OFFICE: 683, Preservation Consultants, Inc.

25.5. DATE RECEIVED: 1/10/80

25.6. COMMENTS: _____



DESCRIPTION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
 Survey Field Report/Entry Form
 State Historic Preservation Office
 PO Box 11,000, Columbia, SC 29211
 (803)726-8377

CONTROL NUMBER: 11/91/1193/820-130
county census tract site number

CONTINUATION



SCALE

- 1
- 2
- 3

View

FACADE (EAST ELEVATION)
FRONT & RIGHT ELEVATIONS
ENTRANCE DETAIL

Date taken 8/11/09
 Recorded by DBS, President



SA, Inc.