

IDENTIFICATION

South Carolina Inventory of Historic Places
 Survey Field Form
 South Carolina Department of Archives
 PO Box 11,608, Columbia, SC 29211
 (803) 735-8077

1. CONTROL NUMBER: U / S / 1 / 1 / 8 / 5 / 4 / 2 / 4 / 1 / 0 / 7
country official design of its number record place

2. HISTORIC NAME(S): Alexander Meekins House

3. OTHER NAME(S): Travelside House

4. ADDRESS/LOCATION: Park Ave.

CITY: Rock Hill VICINITY OF: _____ COUNTY: York

5. OWNERSHIP (private) state county federal 6. CATEGORY: building site structure object

7. HISTORIC USE(S): single dwelling multi dwelling other (specify) _____

8. CURRENT USE(S): single dwelling multi dwelling other (specify) _____

9. POTENTIAL: historic district archaeological

10. STATUS/NOTE: listed individually in national register

listed as part of national historic landmark

listed as part of historic district

listed individually in national historic landmark

determined eligible

determined not eligible

determined by review board

rejected by commission

pending Federal nomination

completed final primary information sheet (PIS)

11. NAME OF CONTRIBUTING PROPERTY: _____

PROPERTY DESCRIPTION: when other ID is chosen, enter date under ORIGINAL, RECENTLY ADDED, or ALTERATION

12. CONSTRUCTION DATE: 1830s 13. ALTERATION DATE: _____

14. MATERIALS: 15. COMMERCIAL FORM: _____ 16. ARCHITECTURAL STYLE OR INFLUENCE: _____

17. DESCRIPTION: Select as many responses as appropriate.

a) construction method masonry (M) frame (F) log (L) steel (S) other (O)

b) exterior wall: weatherboard (WB) beaded weatherboard (BB) shingle (SH) flatboard (FB) wood shingle (WS) stucco (ST)

marble tile (TA) brick (BR) brick veneer (BV) stone veneer (SV) cast-stone (CS) marble (MA)

applied roll (AR) synthetic siding (SY) asbestos shingle (AS) pigmented structural glass (PG) other (O)

c) historic core shape: rectangular (R) square (SQ) L (L) T (T) R (R) H (H) octagonal (O) irregular (I) other (O)

d) stories: 1 (1) 2 (2) 3 (3) 4+ (4+) other (O)

e) roof shape: gabled to front (GF) gambrel (GB) hip (HP) cross gable (CG) pyramidal (PY)

flat (FL) truncated hip (TH) gambrel (GB) mansard (MA) salt box (SB) jarhead (JH)

front gambrel & wing (FG) gambrel/hip (GH) not visible (NV) other (O)

f) roof material: composition shingle (CS) pressed metal shingle (PM) wood shingle (WS) slate (SL) built-up (BU)

metal non-metal (MN) corrugated metal (CM) rolled roofing (RR) not visible (NV) other (O)

g) # of chimneys: exterior (EX) interior and (IA) interior (IN) central (CN) flat (FL)

double shoulder (DS) not visible (NV) other (O)

h) chimney material: brick (BR) glazed brick (GB) stone (ST) brick & stone (BS) other (O)

i) foundation: not visible (NV) brick pier (BP) brick pier with fill (BPF) brick (BR) stucco masonry (SM)

stone pier (SP) stone (ST) concrete block (CB) slab construction (SL) basement (BA)

raised basement (RB) other (O)

j) porch height: 1 story (1S) 1 story w/hood (1SW) 2 or more stories (2+) 2 or more w/11th story (2+11)

roofed balcony over 1 story (RBO) other (O)

k) porch width: entrance bay only (EBO) over 1 bay, less than full facade (OF) full facade (FF) 2

facade and left elevation (OLE) facade and right elevation (ORE) facade and both (O)

l) porch roof shape: shed (SD) hip (HP) gable (GA) pedimented gable (PG) flat (FL) engaged (EN)

gambrel/hip or shed (GH) other (O)



10. porch details: checkered posts (CP) curved posts (CP) supports on pedestals (SP) columns (CL) posts (CP) posts (CP) pillars (PL) transoms (TP) balustrade (BA) heavy apron rail (HR) curved balustrade (CB) cast balustrade (CA) cast balustrade (CA) other cast/curved work (CT) enclosed end bay (EB) wood screening (WS) other (O)
11. windows: single (S) double (DB) paired (PA) tripartite (TP) grouped (GP) decorative (DC) display (DI) other (O)
12. pane configuration: 1/1 / 1/1 / 1/1 horizontal (H) fixed pane (FG) glass (GL) burglar/robustness (BR) geometric (GC) other (O)
13. doors: single (S) double (DB) transom (TA) fanlight (FL) sidelights (SL) other (O)
14. decorative elements: cast iron (CI) cast stone (CS) terra cotta (TC) granite (GR) wood (WO) pressed metal (PM) material: marble (MR) other (O)

15. interior features:

16. fireplace: none (N) none visible (NV) garage (GR) garage adjoining area (GA) shed (SD) kitchen (KT)
17. fireplace: cement base (CB) other base (OB) office (OF) barn (BR) tobacco barn (TB) dairy (DA) crib (CR)
18. fireplace: chimney (CM) stone base (SB) privy (PV) well (WL) springhouse (SP) store (ST) other (O)
19. building type: residential (R) residential/commercial (RC) commercial (C) rural (RU) rural community (RCO) industrial (IR) other (O)

20. ARCHITECTURAL DESCRIPTIVE COMMENTS: Slightly projecting entry bay with two windows on either side. Large gabled dormer set into roof; open balcony, with door flanked by windows. Left elevation: 1/1 bay gabled one-story projection. Right elevation: one-story projection with its roofline extended to form side entry portico, with wood posts and balustrade. Long rear-facing pedimented gable dormer, enclosed, with triple 6/1 windows and louvered attic vent above. Small louvered attic vents in both side gable ends.

21. MATERIALS: Aluminum storm windows

22. HISTORICAL INFORMATION

23. THING(S): Religion
24. PERIOD(S): 1913-1940
25. IMPORTANT PERSON(S):
26. ARCHITECT(S): SOURCE:
27. BUILDER(S): SOURCE:

28. HISTORICAL DATA: Built for Dr. Alexander Martin, who lived here while pastor of Oakland Avenue Presbyterian Church (1914-1921). Not shown in 1914 Rock Hill Rates Book; shown as Dr. Martin's residence in 1923 City Directories. In the 1938 City Directory the house is shown as the home of the Thomas Trumbull family. Acquired by Oakland Ave. Pres. Church in 1943.

29. ENVIRONMENTAL TOPOGRAPHY: City Directories & Rates Book; History of Oakland Avenue Presbyterian Church

30. PROGRAM MANAGEMENT

31. AVAILABLE COPIES: Rock Hill 32. PHOTOGRAPHIC: photo Y slides _____ negative Y
33. OTHER DOCUMENTS: survey/lot-plot files (SF) National Register files (NF) tax ass. files (TA) grants files (GR) state historical marker files (SH) environmental review files (ER) other (O) _____

34. RECORDS MAINTENANCE: DRS, Preservation Consultants, Inc.

35. DATE RECORDED: 3/18/80

36. COMMENTS:



CONTINUATION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
 Survey Field Form
 State Historic Preservation Office
 PO Box 11,500, Columbia, SC 29211
 (803)734-6577

CONTIN. NUMBER: 0191-1193-124-307
county census district site number

CONTINUATION:



ENCLOSURE

TITLE
FRAGILE (WOOD) ELEVATION

Date taken: 5/11/68
 Recorded by: DES, P. R. S. G. S. STARTS

