

IDENTIFICATION

South Carolina Inventory of Historic Places
Survey Field Form
State Historic Preservation Office
PO Box 11,088, Columbia, SC 29211
(803) 754-8507

1. CONTROL NUMBER: U 791 71 195 74 24 362
county address city/zip title number record price

2. HISTORIC NAME: Cunningham House

3. OTHER NAME: _____

4. ADDRESS/LOCATION: 119 Confederate Ave.

city: Rock Hill vicinity of: _____ county: York

5. COMMENTS: (print) STUCCO STAINED GLASS FURNITURE SCULPTURE BUILDING ARCHIT. STRUCTURES OBJECTS

6. HISTORIC USE(S): single dwelling multi dwelling other use(s) _____

7. CURRENT USE(S): single dwelling multi dwelling other use(s) _____

8. POTENTIAL: NH WH Historic district archaeological

9. STATUS/DATE: listed individually in National Register _____
name: _____
 listed as part of WH National Historic District _____ contributing non contributing
name of district: _____
 listed individually in National Historic Landmark _____ part of WH district _____
 determined eligible - under objection _____
 NH process _____
 determined WH eligible _____ rejected by review board _____
 referred by review board _____ removed from NH _____
 referred by Washington _____ removed from survey _____
 pending Federal nomination _____ demolished _____
 completed preliminary information on State OFHS _____ nomination on file _____ never processed

10. NUMBER OF CONTRIBUTING PROPERTIES: _____

PROPERTY DESCRIPTION: check either (A) or (B) to choose, enter date under (A) ADDITIONAL DESCRIPTION (SEE) - (1) ALTERATION

11. CONSTRUCTION DATE: 1905 12. ALTERATION DATE: _____

13. MATERIAL FROM: _____ 14. COMMERCIAL FORM: _____ 15. ARCHITECTURAL STYLE OR INFLUENCE: _____

17. DESCRIPTIONS (check as many responses as appropriate).

- a) construction method masonry (M) frame log (L) steel (S) other (O) _____
- b) exterior wall: weatherboard (WB) beaded weatherboard (BWB) shingle (SH) flatboard (FB) wood shingle (WS) stone (ST) other (O) _____
material: terra (T) brick (BR) brick veneer (BV) stone veneer (SV) cast-stone (CS) marble (MR) other (O) _____
saphire wall (SW) synthetic siding (SY) asbestos shingle (AS) plastered structural glass (PG) other (O) _____
- c) historic core shape: rectangular square (S) L (L) T (T) S (S) R (R) octagonal (O) irregular (I) other (O) _____
- d) stories: 1 1 1/2 2 1/2 3 4+ other (O) _____
- e) roof shape: gambrel to front (GF) gambrel (G) hip gable (GA) gable (GB) pyramidal (PY) flat (FL) truncated hip (TH) gambrel (GR) mansard (MA) salt box (SB) porchless (PC) front gable/hip & wing (FG) gambrel/hip (GH) not visible (NV) other (O) _____
- f) roof material: composition shingle pressed metal shingle (PM) wood shingle (WS) slate (SL) built-up (BU) rolled steel metal (RM) corrugated metal (CM) rolled roofing (RR) not visible (NV) other (O) _____
- g) # of chimneys: anterior (A) posterior and (PA) anterior (AN) central (C) flue (FL) double chimney (DC) not visible (NV) other (O) _____
- h) chimney material: brick stacked brick (SB) stone (ST) brick & stone (BS) other (O) _____
- i) foundation: not visible (NV) brick piers (BP) brick pier with fill brick (BR) stacked masonry (SM) stone pier (SP) stone (ST) concrete block (CB) slab construction (SL) basement (BS) raised basement (RB) other (O) _____
- j) porch height: 1 story 1 1/2 story 2 or more stories (M) 2 or more with tiers (M) marked basement over 1 story marked (BM) other (O) _____
- k) porch width: entrance bay only (EO) over 1 bay, less than full facade (FP) full facade (FY) full facade and left elevation (FL) facade and right elevation (FR) facade and both elevations (FB) other (O) _____
- l) porch roof shape: shed (SD) hip (HP) gable (GA) detached gable (DG) flat engaged (EG) gable-on-gable shed (GS) other (O) _____



- 40 porch details: checkered pavers (CP1) normal pavers (CP) supports on pedestals (CSP) columns (CCL) posts (CPL) piers (CPI) pillars (PL) freestanding posts (CSP) balustrade (BBL) masonry apron wall (CMA) normal balustrade (TB) cast balustrade (CB) steel balustrade (SBL) other cast/formed work (CFT) enclosed and low (EEL) insect screening (IS) other (O)
- 41 windows: single double paired (PND) tripartite (CPT) grouped (GRP) decorative (DED) display (DID) other (O)
- 42 pane configuration: material (M) Queen Anne black-pane (QB) copper/brass/other painted (COP) other (O)
- 43 doors: single double transom (TRN) fanlight (FL) sidelights (SL) other (O)
- 44 decorative cladding: cast iron (CII) cast stone (CS) terra cotta (TC) granite (GR) wood (W) pressed metal (PM) material (M) other (O)
- 45 interior features:

46. DETAIL: none none visible (NV) garage (GR) garage rolling area (GRA) shed (SD) stairs (ST) outdoor (OD): lawn house (LH) other house (OH) office (OFF) barn (BN) tobacco barn (TBN) dairy (DA) crib (CR) washhouse (WH) slave house (SH) privy (PRV) well (WB) springhouse (SPH) store (STR) other (O)
47. SURROUNDING: residential residential/commercial (RC) commercial (C) rural (RL) rural community (RCM) industrial (IND) other (O)

48. ADDITIONAL DESCRIPTIVE COMMENTS: Hipped roof with side gable projections. Gable projection with two-light window. Porch deck retains historic entry. Right elevation: projecting gable bay with double 2/2 windows; two-light window in gable end; rear hipped projection. Left elevation: projecting gable at first bay with single window and two-light gable window.

49. ALTERNATION: Modern door at porch deck entry. Some replacement window sash, one-story addition

GENERAL INFORMATION

50. THREATS: _____
51. PERIOD(S): _____
52. IMPORTANT PERSONS: _____
53. ARCHITECT(S): _____ FIRM: _____
54. BUILDER(S): _____ FIRM: _____
55. ADDITIONAL DATA: Appears on 1910 and 1916 Sanborn maps. 1914 Rates Book shows Mrs. M. E. Hany as owner; 1905 & 1906 City Directories list Mary (Mrs. S. H.) Cundingham as owner/occupant.

56. REPORT/FILE SCOPE:

- PROGRAM MANAGER
57. SIGNATURE NAME: Rock Hill 58. PHOTOGRAPH(S): prints Y slides _____ negative Y
59. OTHER DOCUMENTATION: survey/backup files (SF) national register files (NF) tax lot files (TF) grants files (GF) state historical marker files (SMF) environmental review files (EMF) other (O) _____
60. RECORDS MAINTAINED: DSS, Preservation Consultants, Inc.
61. DATE RECORDED: 10/11/11
62. COMMENTS:



CONTINUATION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
 Survey Field Form/Data Entry Form
 State Historic Preservation Office
 PO Box 11,000, Columbia, SC 29211
 (803)724-8577

CONTROL NUMBER: U-91-1195-122-322
PROPERTY NUMBER COUNTY DISTRICT

CONTINUED FROM



Photo #

View of

ECONOMY (S. B. BLDG)

Date taken: 7-11-82Recorded by: JES, R&R EXPLOSIVES CONSULTING