

IDENTIFICATION

South Carolina Inventory of Historic Places
Survey Field Form/State Entry Form
State Historic Preservation Office
P.O. Box 16360, Columbia, SC 29216
(803) 734-0377

1. FEDERAL NUMBER: 1 1 2 1 1 0 5 1 2 4 4 3 6 6
county census district site number
2. HISTORIC NAME(s): Williamson House
3. OTHER NAME: _____
4. ADDRESS/ADDRESS: 143 Confederate Ave.

SITE: Rock Hill VICINITY OF: _____ COUNTY: York

5. DOMINANT MATERIAL: stone stucco concrete fabric(s) log(s) building(s) stone structure(s) object(s)
7. HISTORIC METHOD: single dwelling multi dwelling other (specify) _____
8. HISTORIC METHOD: single dwelling multi dwelling other (specify) _____
9. POTENTIAL: OR historic district archaeological
10. EVALUATION:
 listed individually in National Register _____
 listed as part of a historic district _____ contributing non-contributing
 listed individually in National Register landmark _____ part of an historic _____
 determined eligible other objection _____
 NHP process _____
 determined eligible _____ rejected by review board _____
 deferred by review board _____ removed from NR _____
 removed by withdrawal _____ removed from survey _____
 pending federal nomination _____ delisted _____
 completed Preliminary Information Sheet (PIS) _____ nomination on file _____
 never processed _____

11. NAME OF CONTRIBUTING PROPERTY: _____
- PROPERTY DESCRIPTION: when other (C) is chosen, enter data under **II. LOCATION, DESCRIPTIVE COMMENTS** or **II. ALTERNATE**
12. CONSTRUCTION DATE: 1900s II. ALTERNATE DATE: 1900s
13. VERIFIABLE FROM: _____ II. COMMERCIAL FROM: _____ III. ARCHITECTURAL STYLE OR INFLUENCE: _____

14. DESCRIPTION: Select as many responses as appropriate.

- a) construction method: Masonry (MS) Iron (IR) Log (LG) Steel (STL) Other (O)
- b) exterior wall: weatherboard (WB) board weatherboard (BWB) shingle (SH) flushboard (FB) wood shingle (WS) stone (ST) other (O)
 material: Slaty (SL) brick (BR) brick veneer (BVR) stone veneer (SVR) cast stone (CS) marble (MR)
 masonry full (MFP) synthetic stucco (SP) asbestos shingle (AS) pigmented structural glass (PSG) other (O)
- c) historic core shape: rectangular (R) square (SQ) L (L) T (T) U (U) R (R) irregular (IR) triangular (TR) other (O)
- d) stories: 1 2 3 or other (O)
- e) roof shape: gabled (or hipped) (G) gable/hip (GH) hip (H) cross gable (CG) gambrel (GR) flat (FL) truncated hip (TH) gambrel (GB) hipped (HP) salt box (SB) gambrel (GB) front gambrel & wing (FGW) gambrel-hip (GHW) non-visible (NV) other (O)
- f) roof material: composition shingle (CS) pressed metal shingle (PMS) wood shingle (WS) slate (SL) building (BL) rolled steel metal (RSM) corrugated metal (CM) rolled roofing (RR) non-visible (NV) other (O)
- g) # of chimneys: exterior interior and interior exterior flue (FL)
- double chimneys (DC) non-visible (NV) other (O)
- h) chimney material: brick (BR) glazed brick (GB) stone (ST) brick & stone (BS) other (O)
- i) foundation: non-visible (NV) brick pier (BP) brick pier with fill (BPF) brick (BR) glazed masonry (GM)
 stone pier (SP) stone (ST) concrete block (CB) slab construction (SC) basement (BS)
 raised basement (RB) other (O)
- j) porch height: 1 story (1S) 1 story w/dash (1SD) 2 or more stories (2+) 2 or more with stairs (2+ST)
 roofed balcony over 1 story high (R1) other (O)
- k) porch width: entrance bay only (EBO) over 1 bay, less than full facade (1+FF) full facade (FF) 2+ bays and left elevation (2+LE) facade and right elevation (2+RE) facade and both elev. (2+BE) other (O)
- l) porch roof shape: shed (SD) hip (HP) gable (GB) pedimented gable (PG) flat (FL) gabled
- gambrel-hip (GHR) other (O)



13. porch details: clustered posts (00P) turned posts (01P) supports on pedestals (02P) columns (03P) posts (04P) piers (05P) pillars (06P) freestanding posts (07P) balustrade (08A) masonry base wall (09A) turned balusters (01B) cast balusters (02B) flat balusters (03B) other cast/turned work (04B) enclosed end bay (05B) smart screening (11) other (12)
14. window: single (00L) double (01L) paired (02D) tripartite (03T) grouped (04P) decorative (04C) vitages (010) other (11)
15. pane configuration: 1/1 inscribed (01) Queen Anne black-glass (02) burglar/fireproof glass (03) other (04)
16. pane: single (00A) double (01A) transom (02A) half-light (03A) sidelights (04A) other (11)
17. decorative element: cast iron (01) cast stone (02) terra cotta (03) granite (04) wood (05) pressed metal (06) metal (07) other (11)
18. interior features: _____
19. HISTORY: none (0) none visible (00) garage (01) group w/living area (02) shed (03) kitchen (04)
20. UTILIZATION: tenant house (1A) other house (00) office (01F) barn (02B) tobacco barn (03B) dairy (04A) crib (05) workshop (06) slave house (07A) privy (07F) well (08L) springhouse (09) store (10) other (11)
21. RESIDENCE TYPE: residential (0) residential/commercial (0A) commercial (01) rural (02) rural community (03) industrial (04) other (11)

22. ADDITIONAL DESCRIPTIVE COMMENTS: Large gambrel dormer over projecting entry bay, with wood shingles, deeply recessed rounded arch with two-light window. Two pedimented gable dormers with double transom windows. Projecting gable bay at right with three 1/1 windows and rear hipped extension with exterior chimney; shed porch at right elevation.

23. ALTERATIONS: Front porch enclosed at either end; 2nd bath added and house converted into two apartments; asbestos siding within porch 1930s. Entire structure underpinned, porches refloored, ceilings lowered at that time. Shed porch enclosed, roof added over its entry.

HISTORICAL INFORMATION

24. THESIS: _____
25. REFERENCES: _____
26. SPECIAL REFERENCES: _____
27. ARCHITECTURE: _____ SOURCE: _____
28. REFERENCES: _____ SOURCE: _____
29. HISTORICAL DATA: First owned by Mrs. Jane Koch Kerr; later owned by Ned Marshall family, then by Williamson family after 1904s. Their niece sold house to present owner in 1953. Appears on 1910 Sanborn map; 1914 Rates Book shows J. L. Williamson as owner.

30. INTERVIEW/VIEW/RESEARCH: Mary Lucile Allen, 143 N. Confederate Ave.

PROGRAM MANAGEMENT

31. USABLE NAME: Rock Hill 32. PHOTOGRAPH (TYPE) prints Y slides _____ negative Y
33. OTHER INFORMATION: survey book-up files (01) National Register files (02F) tax act files (03A) grants files (03F) state historical marker files (04F) environmental review files (05F) other (11)
34. OTHER CONSULTING: DES, Preservation Consultants, Inc.
35. DATE RECORDED: 10/1/10
36. COMMENTS: _____



CONTINUATION AND PHOTOGRAPHS

South Carolina Inventory of Historic Places
 Survey Field Form/State Entry Form
 State Historic Preservation Office
 PO Box 15, 601, Columbia, SC 29211
 (803) 732-8507

CONTROL NUMBER: 16191 / 1105 / 224 / 276 / 6
CLASH HOUSE DATE NO LN
HOUSE DATE NO LN

CONTINUATION



Photo #

1

Photo of

FRANCE (S. S. BURN)



Date taken: 8/10/05
 Recorded by: DR. PRESERVATION CONSULTANTS