

IDENTIFICATION

1. COUNTY NUMBER: 11 1 2 3 4 5 6 7 8 9 10 11
COUNTY OFFICE DISTRICT
UNITED STATES

South Carolina Inventory of Historic Places
 Survey Field Form
 State Historic Preservation Office
 PO Box 11,048, Columbia, SC 29211
 (803) 732-8377

2. HISTORIC NAME: Hough House

3. OTHER NAME: _____

4. ADDRESS/LOCATION: 132 Confederate Ave.

CITY: Rock Hill VICINITY OF: _____ COUNTY: York

5. NATIONAL PERIOD: STATE: COUNTY: FEDERAL: & FEDERAL: STATE: COUNTY: FEDERAL:

6. ARCHITECTURE: single dwelling multi dwelling other (specify): _____

7. CURRENT USE: single dwelling multi dwelling other (specify): _____

8. POTENTIAL: historic district archaeological

9. STATUS/NOTE: listed individually in National Register

listed as part of an historic district contributing non-contributing
 (name of district) _____
 listed individually in National Historic Landmarks part of an historic district _____
 determined eligible for such distinction _____
 not processed _____
 determined not eligible _____ rejected by review board _____
 deferred by review board _____ removed from list _____
 removed by Washington _____
 pending federal nomination _____ delisted _____
 completed preliminary nomination (2004) (2005) _____ nomination on file _____
 never processed _____

11. NAME OF CONTRIBUTING PROPERTY: _____

PROPERTY DESCRIPTION: when other (1) is chosen, enter data under ADDITIONAL DESCRIPTIVE COMMENTS or ALTERNATION

12. CONSTRUCTION DATE: 1915c 13. ALTERNATION DATE: _____

14. RESIDENCE FORM: _____ 15. COMMERCIAL FORM: _____ 16. ARCHITECTURAL STYLE OR INFLUENCE: _____

17. DESCRIPTION: Select as many responses as appropriate.

a) construction method masonry (MNS) frame (FRM) log (LOG) steel (STL) other (O) _____

b) exterior wall weatherboard (WB) beaded weatherboard (BWB) shingle (SH) flushboard (FB) wood shingle (WS) stucco (STC) _____

material siding (SNG) brick (BRK) brick veneer (BRV) stone veneer (STV) cast-stone (CS) marble (ML) _____

asphalt roll (ASR) synthetic siding (SYN) asbestos shingle (ASG) aluminum structural glass (ALG) other (O) _____

c) historic core shape rectangular (RT) square (SQ) L (L) T (T) U (U) H (H) octagonal (OG) irregular (IR) other (O) _____

d) stories 1 1 1/2 (1) 2 1/2 3 4+ other (O) _____

e) roof shape gabled to front (GF) gabled/stepped (GS) hip (HP) cross gable (CG) pyramidal (PY) _____

flat (FL) truncated hip (TH) gambrel (GM) mansard (MAN) salt box (SB) pent/steep (PS) _____

front gable/hip & wing (FG) gable/hip (GH) not visible (NV) other (O) _____

f) roof material composition shingle (CS) pressed metal shingle (PMS) wood shingle (WS) slate (SL) built-up (BU) _____

rolled steel metal (RSM) corrugated metal (CM) rolled roofing (RR) not visible (NV) other (O) _____

g) # of chimneys exterior (EX) interior and (IN) 1 interior (1) central (CN) flag (FL) _____

double chimney (DC) not visible (NV) other (O) _____

h) chimney material brick (BR) stuccoed brick (SB) stone (ST) brick & stone (BS) other (O) _____

i) foundation not visible (NV) brick pier (BP) brick pier with fill (BPF) brick (BR) stuccoed masonry (STM) _____

stone pier (SP) stone (ST) concrete block (CB) slab construction (SL) basement (BS) _____

retired basement (RB) other (O) _____

j) porch height 1 story (1S) 1 story wider (1W) 2 or more stories (2+) 2 or more with stairs (2S) _____

porch had ramp over 1 story tapered (PT) other (O) _____

k) porch width entrance less than (ENT) over 1 bay, less than full facade (1-F) full facade (FF) _____

facade and full elevation (FA) facade and right elevation (FR) facade and porch (FP) _____

l) porch roof shed (SH) hip (HP) gable (GA) pentagonal (PO) flat (FL) engaged (EG) _____

gallivan/hip (GH) other (O) _____



2
P (2)

17. porch details: sheltered posts (2PF) turned posts (2PT) supports on pedestal (2SP) columns (2CL) posts (2PO) piers (2PI) pillars (2PL) freestanding posts (2FP) balustrade (2BA) masonry apron wall (2MA) turned balustrade (2TB) cast balustrade (2CB) steel balustrade (2SL) other constructed work (2OT) enclosed and bay (2EB) insect screening (2IS) other (2I)

18. window: single (2S) double (2DL) paired (2PR) tripartite (2TP) grouped (2GR) decorative (2DO) display (2DI) other (2O)

19. pane configuration: 1/2 / 1/2 triangular (TR) leaded lead glass-pane (LGP) longitudinal-pane (GNP) geometric (GEO) other (O)

20. glazing: single (2S) double (2DL) tripartite (2TP) fulllight (2FL) sidelights (2SL) other (2O)

21. decorative glazing: cast iron (CI) cast stone (CS) terra cotta (TC) granite (GR) wood (WO) pressed metal (PM) enameled (EN) other (O)

22. interior features:

1A. ROOMS: none (2N) none visible (2NV) garage (2AG) garage w/ living area (2AL) shed (2SD) kitchen (2IT)

2A. UTILITIES: central house (TH) other house (OH) office (OFF) barn (2BN) tobacco barn (2TB) dairy (2AI) crib (2CR) greenhouse (2GH) stove house (2SH) privy (2PV) well (2WL) well (2WL) springhouse (2PH) store (2ST) other (2I)

1B. SETTLEMENT: residential (2R) residential/commercial (2RC) commercial (2C) rural (2RU) rural community (2RCU) industrial (2IN) other (2I)

23. ADDITIONAL DESCRIPTIVE COMMENTS: Hipped roof with rear hipped projection. Bay window on porch with double window; double porch posts atop apron wall. Right elevation has side entry with simple stoop; at center bay of second level is long horizontal eight-light window. Left elevation has hipped bay window projection with double window. Brick pier foundation with brick fill.

24. ALTERNATES:

HISTORICAL INFORMATION

25. DEDUCTIONS:

26. REFERENCES:

27. IMPORTANT PERSONS:

28. ARCHITECTS: _____ SOURCE: _____

29. BUILDERS: _____ SOURCE: _____

30. HISTORICAL DATA: Earlier structure on site is shown on 1900 Sanborn map as having been destroyed by fire. This house appears on 1916 and 1925 maps. 1916 Paces Book lists Mrs. C. S. Cramer as owner; City Directory for 1905 shows Mrs. F. A. Hough as resident; Miss Eva S. Hough, a teacher at Dunster Avenue School, and Miss Inez Hough were living here in 1909.

31. INFORMATION SOURCES:

PHOTO MANAGEMENT

32. PHOTOGRAPHIC WORK: Rock Hill 3A. PHOTOGRAPHER(S): print Y slide _____ negative Y

33. OTHER DOCUMENTATION: survey back-up files (2BF) national register files (2NF) tax and files (2TF) grants files (2GF)

34. OTHER HISTORICAL WORK: files (2HF) environmental review files (2EF) other (2O) _____

35. RECORD ANALYSIS: DES, Preservation Consultants, Inc.

36. DATE RECORDED: 8/12/03

37. COMMENTS:



