

South Carolina Statewide Survey Site Form  
State Historic Preservation Office  
P.O. Box 11669 • Columbia • SC • 29211 • (803)734-8867

IDENTIFICATION

1. Control Number 11-91-0000 / 414 0000 2. NR Milestone Index # \_\_\_\_\_

3. Historic name(s): 1877/1878 1877/1878 original place store

4. Common name: \_\_\_\_\_

5. Address/location: McLennanella Bay, SE side, .1 mi. SW of Falls Rd.

City: \_\_\_\_\_ Vicinity of: \_\_\_\_\_ County: York

6. Ownership: private (1) city (2) county (3) state (4) federal (5) 8. Current use(s): single dwelling (1) multi dwelling (2)

7. Category: building (1) site (2) structure (3) object (4) 9. Commercial (3) other (4)

10. Potential: NR (1) NR Historic District (2) archaeological (3)

11. Status/Date: listed individually in National Register 11-91 date \_\_\_\_\_

\_\_\_\_\_ listed as part of NR Historic District 11-91 Name of District \_\_\_\_\_  
\_\_\_\_\_ contributing \_\_\_\_\_ non-contributing \_\_\_\_\_  
\_\_\_\_\_ listed individually National Historic Landmark 11-91 \_\_\_\_\_ part of NR Historic District 11-91 \_\_\_\_\_  
\_\_\_\_\_ determined eligible \_\_\_\_\_ owner objection 11-91 \_\_\_\_\_ DCR process 11-91 \_\_\_\_\_  
\_\_\_\_\_ determined NOT eligible \_\_\_\_\_ \_\_\_\_\_ rejected by review board 11-91 \_\_\_\_\_  
\_\_\_\_\_ deferred by review board \_\_\_\_\_ \_\_\_\_\_ removed from NR 11-91 \_\_\_\_\_  
\_\_\_\_\_ approved by Washington \_\_\_\_\_ \_\_\_\_\_ removed from survey 11-91 \_\_\_\_\_  
\_\_\_\_\_ pending federal nomination \_\_\_\_\_ \_\_\_\_\_ demolished \_\_\_\_\_  
\_\_\_\_\_ completed Preliminary Information Sheet (PIS) 11-91 \_\_\_\_\_ \_\_\_\_\_ nomination on file/never processed 11-91 \_\_\_\_\_

12. Number of contributing properties: \_\_\_\_\_

PROPERTY DESCRIPTION: When other (3) is chosen, enter data on reverse side under category 26 or 27.

13. Construction Date 1878 14. Alteration Date \_\_\_\_\_ 15. Architectural style or influence \_\_\_\_\_

16. Commercial Form - circle appropriate response(s)

- |                            |                          |                   |                           |
|----------------------------|--------------------------|-------------------|---------------------------|
| A) 2-part commercial block | D) marked vertical block | G) simple front   | I) Central block w/ wings |
| B) 1-part commercial block | E) 2-part vertical block | H) vault          | J) covered block          |
| C) enclosed window wall    | F) 3-part vertical block | I) enclosed block | K) other                  |

17. DESCRIPTIONS: (select as many responses as appropriate)

- A) HISTORIC CORNER SHAPE**  
rectangle (1)  
square (2)  
L (3)  
T (4)  
U (5)  
H (6)  
scalloped (7)  
irregular (8)  
other (9)
- B) STORES**  
1 story (1)  
1 1/2 stories (2)  
2 stories (3)  
3 1/2 stories (4)  
3 stories (5)  
other (6)
- C) PORCH HEIGHT**  
1 story (1)  
1 story w/ deck (2)  
1 or more stories (3)  
2 or more with tier (4)  
covered balcony over 1 story  
high (5)  
other (6)
- D) HISTORIC CORNER SHAPE**  
gable (end on top) (1)  
gable (external) (2)  
hip (3)  
cross gable (4)  
pyramidal (5)  
flat (6)  
inverted hip (7)  
gambrel (8)  
mansard (9)  
cath roof (10)  
pitched (11)  
gable-on-hip (12)  
mono-pitch (14)  
not visible (15)  
other (16)
- E) NORTH WIDTH**  
entrance bay only (1)  
over 1 bay, less than full  
breadth (2)  
full breadth (3)  
breaks in full elevation (4)  
breaks in slight elevation (5)  
breaks in both elevations (6)  
other (7)
- F) PORCH ROOF SHAPE**  
shed (1)  
hip (2)  
gable (3)  
pedimented gable (4)  
flat (5)  
engaged (6)  
partially engaged (7)  
gable-on-hip or shed (8)  
engaged porch eaveless (9)  
other (10)
- G) NUMBER OF STOREYS**  
1 exterior (1)  
1 interior only (2)  
1 interior (3)  
1 exterior (4)  
1 floor (5)  
1 double shell (6)  
not visible (7)  
other (8)
- H) WINDOWS**  
single (1)  
double (2)  
tripartite (3)  
grouped (4)  
decorative (5)  
display (6)  
other (7)
- I) PANE CONFIGURATION**  
transomed (1)  
Queen Anne block glass (2)  
Prairie School/craftsman  
panoramic (3)  
not visible (4)  
gable  
other
- J) SH**  
not  
other
- K) OTHER**  
with  
feather (4)  
sidelight (5)  
other (7)



**K) CONSTRUCTION METHOD**

- masonry (1)
- frame (2)
- log (3)
- steel (4)
- other (5)

**L) EXTERIOR WALLS**

- walboard (3)
- board/walboard (2)
- sliding (3)
- flushboard (4)
- wood shingle (3)
- stone (4)
- tile (7)
- brick (8)
- brick veneer (9)
- stone veneer (10)
- rust stone (11)
- marble (12)
- asphalt wall (15)
- synthetic siding (16)
- aluminum shingle (17)
- pigmented structural glass (18)
- other (19)

**M) HISTORIC OUTBUILDINGS AND STRUCTURES**

- none (1)
- none visible (2)
- garage (3)
- garage w/ living area (4)
- shed (5)
- kitchen (6)

- stair house (7)
- other house (8)
- office (9)
- lawn (10)
- entrance hall (11)
- dairy (12)

- crib (13)
- smokehouse (14)
- shed house (15)
- porch (16)
- well (17)
- springhouse (18)

- store (19)
- windmill (20)
- chicken coop (21)
- well (22)
- walldozer (23)
- rust well (24)
- other (25)

**19. SURROUNDINGS:** residential (3) residential/commercial (2) commercial (5) rural (4) rural community (5) industrial (6) other (7)

**20. ADDITIONAL DESCRIPTIVE COMMENTS:** B. teacherage A) 2-story rear ell. D) gable dormer

**11. ALTERATIONS:** Alterations: difficult to tell what original structure was; front facade has been altered and porch is not original; nonhistoric vinyl siding obscures details

**HISTORICAL INFORMATION**

12. Theme(s): \_\_\_\_\_ 13. Period(s): \_\_\_\_\_ 14. Important person: \_\_\_\_\_

15. Architect(s): \_\_\_\_\_ Source: \_\_\_\_\_

16. Builder(s): \_\_\_\_\_ Source: \_\_\_\_\_

17. Historical data: \_\_\_\_\_

18. Interview/Bibliography: \_\_\_\_\_

**PROGRAM MANAGEMENT**

19. Quadrangle name: Rock Hill West 20. Photographs: print (3) slides (2)

21. Other documentation: survey back up files (1) National Register files (1) net w/ files (2) grant files (4) state environmental review files (6) HABS/HARIS (7) CHSAA (8) other (9) \_\_\_\_\_ files (5)

22. Recorder name/file: The Ingers Company, Gainesville, GA 23. Date recorded: 3 / 20 / 93

**N) PORCH DETAILS**

- clawfoot posts (1)
- turned posts (2)
- supports on pedestals (3)
- columns (4)
- posts (5)
- piers (6)
- pillars (7)
- bracketing posts (8)
- balustrade (9)
- open wall (10)
- turned balustrade (11)
- decorative stone balustrade (12)
- slat balustrade (13)
- other non-turned work (14)
- stone screening (15)
- paneled screens (16)
- other (17)

**O) CHIMNEY MATERIAL**

- brick (1)
- masonry brick (2)
- stone (3)
- brick & stone (4)
- other (5)

**P) ROOF MATERIAL**

- composition shingle (1)
- pressed metal shingle (2)
- wood shingle (3)
- tile (4)
- ribbed stone metal (5)
- other metal (6)
- rolled roofing (7)
- syn. visible (8)
- tin (9)
- other (10)

**Q) FOUNDATION**

- syn. visible (1)
- brick pier (2)
- brick pier with (3)
- brick (4)
- stucco masonry (5)
- stone pier (6)
- stone (7)
- concrete block (8)
- slab construction (9)
- basement (10)
- raised basement (11)
- other (12)

**R) DECORATIVE ELEMENT MATERIAL**

- rust iron (7)
- pressed metal (2)
- cast iron (3)
- granite (4)
- marble (5)
- rust stone (6)
- brick (7)
- wood (8)
- pigmented glass (9)
- stone (10)
- stucco (11)
- other (12)

**S) INTERIOR FEATURES**

- 
- 
- 
-

South Carolina Statewide Survey Site Form  
CONTINUATION AND PHOTOGRAPHS

Control Number 11 / 91 / 0000 / 434 2035  
county census designated place site #

Continuation: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

(Use grid for sketching)



Photo Index # View of N, S, E, W

52-20 Front & L. Side M

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Date Taken/Recorded by: 1/83, The Jorgas Co.